

Oil Cons.  
N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BP America Production Company

3. Address and Telephone No.

P.O. Box 1089, Eunice, NM 88231

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter B, Section 10, T18S, R27E  
710' FNL & 1830' FEL

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Empire Abo Unit "M 11"

9. API Well No.

30.015.00853

10. Field and Pool, or exploratory Area

Empire Abo

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

CIBP @ 5650' w/25 sxs cmt

03.19.03: MIRUPU. NDWH. NUBOP.

03.20.03: PU 2-3/8" tbg. Tag CIBP @ 5650'.

03.21.03: RU cmt truck. Circ w/lel w/9.5 KCL mud. Spot 25 sxs cmt on top of CIBP. Press test csg. Fluid coming out around wellhead. POH. RIH w/pkr & tbg to 4681'.

03.24.03: Set kr & squeeze 50 sxs cmt. WO"C 2 hrs. POH w/pkr & tbg.

03.25.03: Tag plug @ 4600'. POH. RU wireline & perf @ 2950'. POH & RIH w/pkr & tbg. Set @ 2790'. Squeeze 35 sxs cmt. POH w/tbg. RU wireline & perf @ 1064' POH. RIH w/tbg & pkr. Set @ 900'.

03.26.03: RU pump truck & squeeze 50 sxs cmt. POH. RU wline. WOC 3 hrs. Tag plug @ 960'. RU wireline & perf @ 150'. POH. NDBOP. NUWH. Circ 80 sxs cmt. NDWH & fill WH to surf. RDPU & equipment. Cut off wellhead. Install dry hole marker. Cut off dead men and clean location. Well P&A'd.

APPROVED

APR 16 2003

LEO BABYAK  
PEOLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Signed

Title Sr. Administrative Assistant

Date 04.15.03

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: