Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources			Revised June 10, 2003 WELL API NO.			
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-015-21582			
District III 1220 South St. Francis Dr.				5. Indicate Type STATE	of Lease ☐ FEE ☐	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6. State Oil & Ga			
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name o	r Unit Agreement Nar	ne
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Brainard Gas Cor	m	
PROPOSALS.)			8. Well Number			
1. Type of Well: Oil Well			ECEIVED	2		
2. Name of Operator	Onci			9. OGRID Numb	per	
Devon Energy Production Company, LP			EP 2 9 7004	6137		
3. Address of Operator 20 North Broadway, Suite 1500, Oklahoma City, Oklahoma 73102		1020	10. Pool name or Wildcat Atoka Penn (Pro Gas)			
4. Well Location	ianoma erty, Oktanoma 73	102		1 Moka 1 cmi (110	Gasj	
	0 0 0 1 37	.9	1. 1 4.	505 6 . 6	d 12	
Unit Letter B : 1180 feet from the North line and 1505 feet from the East line						
Section 11	Township 18S		inge 26E	Edd	y County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.,						
12 Check A	3307' GL; 3321' RKB ppropriate Box to Indi	cate N	ature of Notice	Report or Other	· Data	
NOTICE OF IN		cate iv		SEQUENT RE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	\boxtimes	REMEDIAL WOR		ALTERING CASING	i 🔲
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.□	PLUG AND	
<u> </u>			CASING TEST A	ND 🗆	ABANDONMENT	
	COMPLETION		CEMENT JOB			
OTHER:			OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
Devon received approval to TA this well on 7/16/04. Upon further review, Devon wishes to plug and abandon this well.						
				. •		
 Pull existing 2-3/8" production tubing and packer from well. Set CIBP at 8600' and cap w/ 50' cement. 						
3. Circulate wellbore with 9.0# ppg r						
4. Set 150' cement plug from 6450'						
5. Cut 4-1/2" casing at 2300' and ret						
6. Set 150' cement plug from 2200' f7. Set 150' cement plug from 1925' f			T.C. a.l.			
8. Set 150' cement plug from 1125' to 1275'. WOC. Tag plug.				vork requires an		
9. Set 60' surface plug. WOC. earthen				pit, a permit must		
10. Cut casings off 3' below ground level. Set dry hole marker. 11. Restore location. be approximately approxima			oved <u>prior</u> to			
			ction of the $pit(s)$.			
					π(s).	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Romme D. S.	ack TITLE	: Engir	neering Technician	DAT	E9/27/04	
Type or print name Ronnie G. Slack	E-mail address:	Ronnie.	.Slack@dvn.com	Telephone	e No. 405-552-4615	
(This space for State use)						
APPROVED BY Mit Haukin TITLE Field Sugar DATE & Set						

