Submit 3 Copies To Appropriate District Office	State of New M			Form C-1	
District I	Energy, Minerals and Nat	tural Resources	<u>,</u>	Revised June 10, 20	003
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
District II			30-015-02254		
1301 W. Grand Ave., Artesia, NM 88210	Glain Ave., Altesia, NVI 66210		5. Indicate Type of Lease		
District III			STATE X FEE		
000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		6. State Oil & Ga		\neg	
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		o. Santo on to ou		
	CES AND REPORTS ON WELL	S	7 Lease Name or	r Unit Agreement Nam	e
(DO NOT USE THIS FORM FOR PROPOS			7. Doube Name of	Chie rigioomone rum	
DIFFERENT RESERVOIR. USE "APPLIC			East Millman Un	it	
PROPOSALS.)	,		8. Well Number	ut	-
1. Type of Well:					
Oil Well Gas Well Other TA		WED	161		
2. Name of Operator		9. OGRID Number			
	4 000A		9. OGRID Number 020451		
SDX Resources, Inc.	OCT 1				
3. Address of Operator	OCD-M	HTERIA	10. Pool name or Wildcat		
PO Box 5061, Midland, TX 79704			Millman, YT-7R,	East (46555)	
4. Well Location					
Unit Letter_I:	_1980 feet from theSouth	line and _660	feet from t	heEastline	ļ
					1
Section 14	Township 19S	Range 28E	NMPM E	ddy County	
	11. Elevation (Show whether D	R, RKB, RT, GR, etc.)		og og Ar-Killings byk	
	3391' GR	•			
12 Check A	appropriate Box to Indicate	Nature of Notice	Report or Other	Data	
			•		
NOTICE OF IN			SEQUENT RE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K 📙	ALTERING CASING	_
	_				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.		
	CHANGE PLANS		_	PLUG AND [ABANDONMENT	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AN	_		
	CHANGE PLANS		_		
PULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPLETION	CASING TEST AN	4D 🗆	ABANDONMENT	
PULL OR ALTER CASING OTHER:	CHANGE PLANS MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB OTHER: Temp	ND Dorarily Abandon	ABANDONMENT X	
OTHER: 13. Describe proposed or complete.	CHANGE PLANS MULTIPLE COMPLETION Clearly state al	CASING TEST AN CEMENT JOB OTHER: Temp	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or complete of starting any proposed wo	CHANGE PLANS MULTIPLE COMPLETION	CASING TEST AN CEMENT JOB OTHER: Temp	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or complete.	CHANGE PLANS MULTIPLE COMPLETION Clearly state al	CASING TEST AN CEMENT JOB OTHER: Temp	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion.	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alork). SEE RULE 1103. For Multiple Complete Comple	CASING TEST AN CEMENT JOB OTHER: Temp	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or complete of starting any proposed wo	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alork). SEE RULE 1103. For Multiple Complete Comple	CASING TEST AN CEMENT JOB OTHER: Temp	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion.	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alork). SEE RULE 1103. For Multiple Complete Comple	CASING TEST AN CEMENT JOB OTHER: Temp	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion.	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon	ABANDONMENT X es, including estimated	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon d give pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified.	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At	oorarily Abandon d give pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending from the complete state of the comp	CASING TEST AN CEMENT JOB OTHER: Temple I pertinent details, and iple Completions: Attended to the completion of the co	oorarily Abandon d give pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending from the complete state of the comp	CASING TEST AN CEMENT JOB OTHER: Temple I pertinent details, and iple Completions: Attended to the completion of the co	oorarily Abandon d give pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or complos of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to CLARA COLORS COLO	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending from the placed in TA status pend	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and in the completions: At the completion of the completion	porarily Abandon digive pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart.)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending from the placed in TA status pend	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and in the completions: At the completion of the completion	porarily Abandon digive pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or complos of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to CLARA COLORS COLO	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending from the placed in TA status pend	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and in the completions: At the completion of the completion	porarily Abandon digive pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or complos of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to CLARA COLORS COLO	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alrk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending from the placed in TA status pend	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and in the completions: At the completion of the completion	porarily Abandon digive pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple senter approved - O F - O F	date
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart. SDX Resources is requesting well to the starting wel	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alark). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending for the pl	CASING TEST AN CEMENT JOB OTHER: Temple pertinent details, and iple Completions: At a state of my knowledge to the complete o	porarily Abandon digive pertinent date tach wellbore diagra	ABANDONMENT X es, including estimated am of proposed comple	date
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart. SDX Resources is requesting well to the starting wel	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state alark). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending for the pl	CASING TEST AN CEMENT JOB OTHER: Temp I pertinent details, and in pertinent details. At the pertinent development. The pertinent details and in pertinent development.	porarily Abandon digive pertinent date fach wellbore diagra Temporery Abandonad Temporery Abandonad To Jacob Ja	ABANDONMENT X es, including estimated am of proposed comple senter approved - O F - O F	date
OTHER: 13. Describe proposed or completion of starting any proposed we or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to I hereby certify that the information and SIGNATURE Type or print name Bonnic Atwater	CHANGE PLANS MULTIPLE COMPLETION Deted operations. (Clearly state all rk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending for above is true and complete to the TITLE	CASING TEST AN CEMENT JOB OTHER: Temp I pertinent details, and in pertinent details. At the pertinent development. The pertinent details and in pertinent development.	porarily Abandon digive pertinent date fach wellbore diagra Temporery Abandonad Temporery Abandonad To Jacob Ja	ABANDONMENT X es, including estimated am of proposed completed among proposed completed are proposed as a second complet	date
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to I hereby certify that the information a SIGNATURE	CHANGE PLANS MULTIPLE COMPLETION Deted operations. (Clearly state all rk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending for above is true and complete to the TITLE	CASING TEST AN CEMENT JOB OTHER: Temp I pertinent details, and in pertinent details. At the pertinent development. The pertinent details and in pertinent development.	porarily Abandon digive pertinent date fach wellbore diagra Temporery Abandonad Temporery Abandonad To Jacob Ja	ABANDONMENT X es, including estimated am of proposed completed among proposed completed are proposed as a second complet	date
OTHER: 13. Describe proposed or completion of starting any proposed wo or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to SDX Resources is requesting well to SIGNATURE Type or print name Bonnie Atwater (This space for State use)	CHANGE PLANS MULTIPLE COMPLETION Letted operations. (Clearly state all rk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending for the above is true and complete to the TITLE E-mail address: batwate	CASING TEST AN CEMENT JOB OTHER: Temp I pertinent details, and in pertinent details. At the pertinent development. The pertinent details and in pertinent development.	porarily Abandon digive pertinent date fach wellbore diagra Temperery Abandoned Telephone Telephone	ABANDONMENT X es, including estimated am of proposed completed among p	date
OTHER: 13. Describe proposed or completion of starting any proposed we or recompletion. Ran pressure test on 10/12/04 (chart SDX Resources is requesting well to I hereby certify that the information and SIGNATURE Type or print name Bonnic Atwater	CHANGE PLANS MULTIPLE COMPLETION Deted operations. (Clearly state all rk). SEE RULE 1103. For Multiple attached). NMOCD notified. be placed in TA status pending for above is true and complete to the TITLE	CASING TEST AN CEMENT JOB OTHER: Temp I pertinent details, and in pertinent details. At the pertinent development. The pertinent details and in pertinent development.	porarily Abandon digive pertinent date fach wellbore diagra Temperery Abandoned Telephone Telephone	ABANDONMENT X es, including estimated am of proposed completed among proposed completed are proposed as a second complet	date

