Office	State of New M	exico	Form C-103
District I	Energy, Minerals and Nat	ural Resources	Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240	0.00		WELL API NO.
District II	OH COMPEDMATION	TOTALION	30-015-22402
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1220 South St. Francis Dr.		STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
District IV	Santa 1 C, 14141 C	7303	0. State Off & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	ES AND REPORTS ON WELL	<u> </u>	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL			7. Lease Name of Olit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICAT			T 00 D
PROPOSALS.)	TONTOR LEASING (TORM C-101)	OK BOOM	Exxon State Comm B
1. Type of Well:			8. Well Number
Oil Well Gas Well Other	m ΤΛ _		1
	, 1A p	RECEIVED	
2. Name of Operator		_ 1	9. OGRID Number
SDX Resources, Inc.		OCT 1 4 2004	020451
3. Address of Operator	Or	D-ADTEOLA	10. Pool name or Wildcat
PO Box 5061, Midland, TX 79704	6.00 C	PARTESIA	Millman, Morrow (81365)
4. Well Location			Iviniman, wortow (01303)
4. Wen Location			
TT 1.7 6	1650 6 6 4 37 4	1: 1 1000	
Unit Letter_G::	1650 feet from theNorth	line and _1980	feet from theEastline
Section 29	Township 19S	Range 28E	NMPM Eddy County
	1. Elevation (Show whether Di	R, RKB, RT, GR, etc.)	
	3407' GR	, , , , ,	
		Jatura of Matica	Donort or Other Date
	propriate Box to Indicate 1		
NOTICE OF INTI	ENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ I	PLUG AND ABANDON 📋	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. PLUG AND
TEMPORARIET ABANDON []	SHANGE LEVIAS	COMMENCE DE	ABANDONMENT
PULL OR ALTER CASING I	MULTIPLE	CASING TEST AN	
	MULTIPLE [] COMPLETION		ND ∐
	.CRAPLE IN AN	CEMENT JOB	
·	SOM EETION	1	
	<u>_</u>	OTHER: Tom	porerity Abandan V
OTHER:			porarily Abandon X
OTHER:		<u> </u>	oorarily Abandon X I give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete	☐ ed operations. (Clearly state all	pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work	☐ ed operations. (Clearly state all	pertinent details, and	
OTHER: 13. Describe proposed or complete	☐ ed operations. (Clearly state all	pertinent details, and	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	ed operations. (Clearly state all b. SEE RULE 1103. For Multi	pertinent details, and ple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	ed operations. (Clearly state all b. SEE RULE 1103. For Multi	pertinent details, and ple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multi ached). Test witnessed by Jerry	pertinent details, and ple Completions: At Guye of the NMOC ture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the status	pertinent details, and ple Completions: At a Guye of the NMOC ture development.	If give pertinent dates, including estimated date tach wellbore diagram of proposed completion CD. Semporery Abandonsod Status approved $\frac{1}{10000000000000000000000000000000000$
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the status	pertinent details, and ple Completions: At a Guye of the NMOC ture development.	If give pertinent dates, including estimated date tach wellbore diagram of proposed completion CD. Semporery Abandonsod Status approved $\frac{1}{10000000000000000000000000000000000$
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be a starting that the information above.)	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the status	pertinent details, and ple Completions: At a Guye of the NMOC ture development.	If give pertinent dates, including estimated date tach wellbore diagram of proposed completion CD. Semporery Abandonsod Status approved $\frac{1}{10000000000000000000000000000000000$
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the status	pertinent details, and ple Completions: At a Guye of the NMOC ture development.	If give pertinent dates, including estimated date tach wellbore diagram of proposed completion CD. Supporery Abandonad Status approved $\frac{1}{10} = 0.000$ and belief.
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be a starting that the information above.)	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the status	pertinent details, and ple Completions: At a Guye of the NMOC ture development.	If give pertinent dates, including estimated date tach wellbore diagram of proposed completion CD. Semporery Abandonsod Status approved $\frac{1}{10000000000000000000000000000000000$
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be a superior of the start of the	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the latest to th	pertinent details, and ple Completions: At a Guye of the NMOConture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion cD. Semporery Abandonad Status approved to the completion of
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be I hereby certify that the information about the starting starting with the starting starting well to be SIGNATURE.	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the status	pertinent details, and ple Completions: At a Guye of the NMOConture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion cD. Semporery Abandonad Status approved and belief. DATE_10/13/04
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be a superior of the start of the	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the latest to th	pertinent details, and ple Completions: At a Guye of the NMOConture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion cD. Semporery Abandonad Status approved and belief. DATE_10/13/04
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be I hereby certify that the information about the starting starting in the starting starting in the starting starting in the starting	ed operations. (Clearly state all). SEE RULE 1103. For Multi- ached). Test witnessed by Jerry placed in TA status pending for over is true and complete to the I	pertinent details, and ple Completions: At a Guye of the NMOConture development.	digive pertinent dates, including estimated date tach wellbore diagram of proposed completion cd. D. Semporery Abandonad Status approved mail /0-/2 = 05 e and belief. DATE_10/13/04 Telephone No. 432/685-1761
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be I hereby certify that the information about the starting starting with the starting starting well to be SIGNATURE.	ed operations. (Clearly state all). SEE RULE 1103. For Multipached). Test witnessed by Jerry placed in TA status pending for the latest to th	pertinent details, and ple Completions: At a Guye of the NMOConture development.	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion CD. Semporery Abandonad Status approved The semporery Abandonad Status approved Abandonad Status approved Abandonad Status approved Abandonad Abandonad Abandonad Abandonad Abandonad Aband
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Ran pressure test on 10/12/04 (chart att SDX Resources is requesting well to be I hereby certify that the information about the starting starting in the starting starting in the starting starting in the starting	ed operations. (Clearly state all). SEE RULE 1103. For Multi- ached). Test witnessed by Jerry placed in TA status pending for over is true and complete to the I	pertinent details, and ple Completions: At a Guye of the NMOConture development.	digive pertinent dates, including estimated date tach wellbore diagram of proposed completion cd. D. Semporery Abandonad Status approved mail /0-/2 = 05 e and belief. DATE_10/13/04 Telephone No. 432/685-1761

