Submit 3 Copies
to Appropriate
District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-49

District Office	2 4 55.	mai resources popularia	Ksamed 1-1-40
DISTRICT I P.O. Box 1940, Hobbs, NM \$8240	OIL CONSERVATION DIVISION		WELL API NO.
DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-015-01483
P.O. Drawer DD, Artesia, NM \$5210	·		S. Indicate Type of Long STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410		·	6. State Oil & Ges Lense No. B-3149
	TICES AND REPORTS ON		
	RPOSALS TO DRILL OR TO DE RVOIR. USE "APPLICATION FO 2-101) FOR SUCH PROPOSALS	OR PERMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well:	1	DECEMED	Red Lake Sand Unit
well. Name of Operator	OTHER	RECEIVED	8. Well No. 27
Mack Energy Corporat	ion	MAR - 2 2004	27
1. Address of Operator P.O. Box 960, Artesia	a, NM 88211-0960	OCD-ARTESIA	9. Pool same or Wildcu Red Lake; Queen-Grayburg-SA
4. Well Location Unit Letter :	2310 Sc	outh Line and 165	O Feet From The East Line
20	~ 17S	28E	NMPM Eddy County
Section	Township 10. Elevation (Show w	Range heiher DF, RKB, RT, GR, etc.)	NMPM Eddy County
	Appropriate Box to India		-
NOTICE OF INT	TENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT XX
PULL OR ALTER CASING		CASING TEST AND CE	ENENT JOB C
OTHER:		OTHER:	
12. Describe Proposed or Completed Opera work! SEE RULE 1103.	tions (Clearly state all pertinent des	ails, and give portinent dates, include	fing estimated date of starting any proposed
2-16-04 Spot 25 sx cr	mt. @ 1705' tag pl	ια @ 1552†	
2-17-04 Perf. 4 holes	s @ 525', set pkr. @	188' sqz. 35 sx c	mt. tag plug @ 383'.
2-17-04 Perf. 4 holes	s @ 250', set pkr. (30' sqz. 35 sx cm	t. displaced cmt. to 150'.
8-5/8" csg.]	s e 60° pump 25 sx c Leave 7" full of cmt	emt. down /" to sur	face out of $8-5/8$ " csg. and outs
2-18-04 Tag plug @ 4	'.		
2-18-04 RDMO. Cut off	f wellhead, install	dry hole marker, &	clean location.
I hereby certify that the information aboya, is tru	s and complete to the best of my knowled	ige and belief.	
I hereby certify that the information above is true SKINATURE	s and complete to the best of my knowled	ke and belief. Agent	DATE 2-20-04
\mathcal{K}	my	_	DATE 2-20-04 TELEPHONE NO. (432) 530-



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor Joanna Prukop

Cabinet Secretary

P/A ot To Release

10/20/04

RECEIVED

OCT 1 5 2004

DDD=ARTESIA

Lori Wrotenberv Director Oil Conservation Division

3 March 2004

Mack Energy Corp. P. O. Box 960 Artesia, New Mexico 88221-0960

API 30-015-01483 Form C-103 Report of Plugging for your Red Lake Sand Unit # 27 J-20-17-28 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been filled and leveled.
- 12. Rat hole and cellar have been filled and leveled.
- X 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Field Rep. II

Frank W. Shenell Production Clark