

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
March 4, 2004

Well API NO.	30-015-29345
5. Indicate Type of Lease	<input checked="" type="checkbox"/> State <input type="checkbox"/> Fee
6. State Oil & gas Lease No.	
7. Lease Name or Unit Agreement Name	Cotton Draw Unit
8. Well Number	81
9. Ogrid Number	6137
10. Pool Name or Wildcat	S Cotton Draw

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

DEVON ENERGY PRODUCTION COMPANY, LP

3. Address and Telephone No.

20 North Broadway, Ste 1500, Oklahoma City, OK 73102

405-228-8209

4. Well Location

Unit Letter L 1650 feet from the South line and 660 feet from the West line
Section 2 Township 25S Range 31E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3437'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- ☒ PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON
☐ TEMPORARILY ABANDON ☐ CHANGE PLANS
☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION
☐ Other _____

SUBSEQUENT REPORT OF:

- ☐ REMEDIAL WORK ☐ ALTERING CASING
☐ COMMENCE DRILLING OPN ☐ PLUG AND ABANDONMENT
☐ CASING TEST AND CEMENT JOB
☒ OTHER Began injection

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.
For Multiple Completions: Attach wellbore diagram or proposed completion or recompletion. If a pit or below-grade tank is involved in the operation, complete the reverse side of this form.

Devon Energy Production Co., LP respectfully requests approval to recomplete as follows:

1. Drill out CIBP @ 7550'.
2. Set cmt retainer @ 7570' & squeeze Delaware perms 7620'-7671' w/ 100 sx Class C cmt.
3. Drill out squeeze & test to 500 psi.
4. Perf Bone Spring 8752'-8768'.
5. Acidize bone Spring perms w/ 1500 gals 7.5% NEFE acid
6. Frac w/ 72,000# sand.
7. Hang on pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Linda Guthrie

TITLE Regulatory Specialist

DATE 10/26/2004

Type or Print name

Linda Guthrie

E-mail Address:

linda.guthrie@dyn.com

Telephone No.

405-228-8209

APPROVED BY

TITLE

DATE

NOV 3 2004

Conditions of approval, if any: