Form 3160-5 (April 2004)

determined that the site is ready for final inspection.)

N.M. Oil Cons. DIV-Dist. 2

1301 W. Grand Avenue UNITED STATES DEPARTMENT OF THE INTERIOR MESIA, NM 88210

FORM APPROVED Expires March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

OMB No. 1004-0135

abandoned well. Use Form 3160-3 (APD) for such proposals.					[NIVI-27000		
					ee or Tribe Name		
SUBMIT IN TRIPLI	CATE - Other instr	uctions on reverse si	de CEIVES	7. If Unit or CA/Aç	greement, Name and/or No.		
Type of Well							
X Oil Well Gas	Well Other	00	T 2 9 2004	8. Well Name and	i No.		
Name of Operator		OCD.	ARTESIA	Prickly Pear	AIE Federal #1		
Yates Petroleum Corporation			0.00	9. API Well No.			
3a. Address 3b. Phone No. (include area code)				30-015-26738			
105 S. 4th Str., Artesia, NM	505-748-1471		10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.,T.,R.,M.,	OR Survey Description)	•		Wildcat Wolfd Springs/Wildd	camp/Wildcat Bone cat Yeso		
				11. County or Par	ish, State		
990'FSL & 990'FEL of Section 23-T20S-R24E (Unit P, SESE)					Eddy County, New Mexico		
12. CHECK APPROPI	LIATE BOX(ES) TO	INDICATE NATURE O	f notice, re	PORT, OR O	THER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off		
X Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
	Casing Repair	New Construction	X Recomplete		Other		
Subsequent Report	Change Plans	Plug and Abandon	Temporarily	Abandon			
Final Abandonment Notice	Convert to Injection	X Plug Back	Water Dispo	sal			
13. Describe Proposed of Completed Operation (cla							
If the proposal is to deepen directionally or reco Attach the Bond under which the work will be							

Yates Petroleum Corporation plans to plugback and recomplete this well as follows: Set a CIBP at 7541' with 35' cement on top. Perforate Wolfcamp 6704'-6722' (19). Stimulate as needed. Swab test for evaluation, could turn to production. If not, set a CIBP at 6654' with 35' cement on top. Perforate Bone Springs 5352'-5364' (13) and 5422'-5438' (17). Stimulate as needed. Swab test for evaluation, could turn to production. If not, set a CIBP at 5302' with 35' cement on top. Perforate Yeso 2414'-2420' (7), 2490'-2510' (21), 2516'-2534' (19), 2544'-2550' (7), 2566'-2570' (5), 2586'-2590' (5) and 2634'-2638' (5). Stimulate as needed. Swab test for evalution. Turn well to production.

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

14. I hereby certify that the foregoing is true and correct		*		
Name (Printed/Typed)				
Tina Huerta		Regulatory Compliance Supervisor		
Signature lina Luerta	Date	October 25, 2004	APPROVED	
) THIS SPACE FOR	FEDERAL O	R STATE OFFICE USE		
Approved by		Title	Date OCT 2 8 2004	
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the su	Office	(ORIG. SGD.) ALEXIS C. SACSO		
which would entitle the applicant to conduct operations thereon.		ALEXIS C. SWOBODA		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime States any false, fictitious or fraudulent statements or representations as to any	for any person	knowingly and willbully to make to	any departmenter and better the endineer	