Form 3160-5 (August 1999)

N.M. Oil Cons. DIV-Dist. 2
UNITED STATES 1301 W. Grand Avenue

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDR	BUREAU OF LAND MANA Y NOTICES AND REPO	GEMINT[[]]。 RTS ON WELL	a, NM 88210 s	5. Lease Se NMNM 35		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
	ÍPLICATE - Other Instru	ictions on reve	orse side	7. If Unit o	r CA/Agreement, Name and/or No.	
1. Type of Well ☐ Oil Well ဩ Gas Well ☐ Other			RECEIVED			
2. Name of Operator Chesapeake Operating, Inc.			JAN 1 0 2005		Dana Federal 9 9. API Well No.	
3a. Address P. O. Box 11050 Midland TX 79702-8050		3b. Phone No. (include area code TES	30-005-6	3583 d Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description 1980' FSL & 660' FWL; Sec. 4, T9S, R25E				Pecos Si	ope;Abo or Parish, State	
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE N	ATURE OF NOTICE,	REPORT, OI	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construct Plug and Abar Plug Back	Reclamation Recomplete		□ Water Shut-Off□ Well Integrity□ Other	
If the proposal is to deepen did. Attach the Bond under which following completion of the ir testing has been completed. Find determined that the site is read Chesapeake, respectfully 1. MIRU. POOH lay dow 2. Contact BLM field rep 3. Load hole w/packer flux.	the work will be performed or provolved operations. If the operational Abandonment Notices shall be for final inspection.) The hereby request permission tubing. The prior to WL operations. The pressure test to 300.	ally, give subsurface ovide the Bond No. or results in a multiple of filed only after all resion to temporal Set a CIBP @ 3	locations measured and true in file with BLM/BIA. Reque completion or recompletion requirements, including reclarity abandon this wellocated. Bail 1 sx of centers.	e vertical depths of ired subsequent rong in a new interval amation, have been by the followerment on plug	g.	
Please su!	dry for final approval. 500	Complet	SEE A	ATTACHEL ONS OF A	FOR	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Brenda Coffman			Accepted for record - NMOCD egulatory Analyst			
Signature Coloman			Date 12/21/2004			
	THIS SPACE	FOR FEDERAL	OR STATE ÖFFICE L	JSE		
Approved by Acl			Title		Date //6/05	
Conditions of approval, if any, as certify that the applicant holds leg which would entitle the applicant						

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 505-627-0272

Conditions of Approval

Requirements for casing integrity test are as follows:

- 1. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 5. Contact the BLM at least 24 hours prior to the scheduled Casing Integrity Test at 505-627-0272.;

Wells that successfully pass the casing integrity test require the following

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy or the original of the pressure test chart.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing.
- 2. A procedure to plug and abandon the well.

Accepted for record - NMOCD

Ref: IM: NM-95-022 (12/16/94)