

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD - Artesia  
FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

5 Lease Serial No

NM-25365

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Neff Federal #3

9. API Well No.

30-015-28281

10. Field and Pool, or Exploratory Area  
Livingston Ridge Delaware

11. County or Parish, State

Eddy NM

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

SWD

2. Name of Operator

OXY USA Inc.

16696

3a. Address

P.O. Box 50250 Midland, TX 79710

3b Phone No. (include area code)

432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

430 FNL 760 FWL NWNW(D) Sec 25 T22S R31E

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

**TYPE OF ACTION**

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☒ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD-8460' PBDT-6050' Perfs-5634-5987'

1.RU slickline unit and check well for fill.

2.Check location for hazardous conditions. Ensure well is dead.

3.MI & RU DDP. NU BOP.

4.POOH w/ Injection Tbg and Packer & LD.

5.If fill is found in step #1, PU work string and RIH to PBDT and circulate hole clean. If no fill found go to step #6.

6.ND BOP and NU Frac valve. RD and MO DDP.

7.Frac well down casing per frac procedure at first available date.

8.MI & RU DDP. ND Frac valve and NU BOP.

9.PU work string and RIH and clean out to PBDT.

10.POOH and LD work string.

11.PU injection tubing, packer and injection BHA and rih and set packer at +/-5500'.

12.Fill casing/tbg annulus with inhibited packer fluid. Test backside to 1000psi. Note: Notify OCD to witness test MIT.

13.Place well on injection and report results to engineer.

Accepted for record - NMOCD

RECEIVED

JUN 13 2011

NMOCD ARTESIA

Accepted for record

NMOCD

7/13/11

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

David Stewart

Title

Sr. Regulatory Analyst

Date

4/19/11

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

SRAS

Date

6-5-11

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFD

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.