

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739	
Facility Name: JL Keel B #52	Facility Type: Oil Producer	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-28098

### LOCATION OF RELEASE

Unit Letter P	Section 06	Township 17S	Range 31E	Feet from the 1310	North/South Line South	Feet from 60	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------	------------------------	-------------

Latitude: 32.8595 Longitude -103.9006 (Release site)

### NATURE OF RELEASE

Type of Release: Produced water/crude	Volume of Release Unknown	Volume Recovered Unknown
Source of Release: Flowline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Feb 2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? Gary Wink	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* The release appeared to have come from a wellhead/stuffing box failure. The released fluid exited the location and entered the pasture on the south side of the location traversing between two sand dunes for approx. 150'. The affected area had visible staining and this was excavated. The pasture area was tilled and reseeded with a native seed mixture. Linn Energy respectfully requests closure of this incident.		
Describe Area Affected and Cleanup Action Taken. The spill area is west from the wellhead and was not contained strictly to the pad area. About 20' by 1' in the pasture area was impacted. This is primarily a sand area with a quick absorption rate. The overall impacted area measured 11,454 sq. ft. DFSI was retained to fully remediate the site according to NMOCD and BLM guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Fred B Wall</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Brian Wall	Approved by Environmental Specialist:	
Title: Construction Foreman II	Approval Date: 8/18/2014	Expiration Date: NA
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/11/14 Phone: 806-367-0645	FINAL	2RP-711

\* Attach Additional Sheets If Necessary