

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739	
Facility Name: JL Keel B #52	Facility Type: Oil Producer	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-28098

LOCATION OF RELEASE

Unit Letter P	Section 06	Township 17S	Range 31E	Feet from the 1310	North/South Line South	Feet from 60	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------	------------------------	-------------

Latitude: 32.8583 Longitude -103.8998

NATURE OF RELEASE

Type of Release: Produced water/crude	Volume of Release 2bbl/6bbl	Volume Recovered 0
Source of Release: Nipple on the Wellhead	Date and Hour of Occurrence 09/16/2012 10 AM	Date and Hour of Discovery 09/16/2012 10:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston-BLM Mike Bratcher- NM OCD	
By Whom? Gary Wink	Date and Hour: 09/17/2012 6:15 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* The nipple at the wellhead incurred a small hole due to corrosion and deterioration. This was replaced.		
Describe Area Affected and Cleanup Action Taken. The spill area is west from the wellhead and was not contained strictly to the pad area. About 20' by 1' in the pasture area was impacted. This is primarily a sand area with a quick absorption rate. The overall impacted area measured 11,454 sq. ft. DFSI was retained to fully remediate the site according to NMOCD and BLM guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Fred B Wall</i>		<u>OIL CONSERVATION DIVISION</u>
Printed Name: Brian Wall		Approved by Environmental Specialist:
Title: Construction Foreman II	Approval Date: 8/18/2014	Expiration Date: NA
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/12/14 Phone: 806-367-0645	FINAL	2RP-1311

* Attach Additional Sheets If Necessary