Received 9/18/2014 NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR OPERATOR									☐ Initia	al Report	\bowtie	Final Report	
Name of Co	ompany: O		Contact: C			1							
Address: 102 S. Main St. Carlsbad, NM 88220						Telephone No.: 575-628-4121							
Facility Name: PIGLET 21 CTB						Facility Type: Battery							
Surface Ow	ner: State	wner:	:			API No.: Lease #: 30-015-39371							
	LOCATION OF RELEASE												
						h/South Line Feet from t		East/West Line		County: Eddy			
Latitude <u>32.8172087 N</u> Longitude <u>-104.173429 W</u>													
NATURE OF RELEASE													
Type of Release: Produced Water							Volume of Release: 30 bbls PW Volume Recovered: -0- bbls PW						
Source of Release: Human Error Load line not disconnected											Hour of Discovery		
Was Immediate Notice Given?							5/16/14 @ 9:00 am 5/63/14 @ 9:00 am If YES, To Whom?						
Yes No Not Required													
, and the second						Jennifer Van Curen @ BLM - email							
By Whom? Chris Jones							Date and Hour: 5/16/2014 12:44 pm						
Was a Water	course Reac	If YES, Volume Impacting the Watercourse.											
☐ Yes ⊠ No													
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken * A driver drove off without disconnecting his load line which caused 20 by 1 cm.													
Describe Cause of Problem and Remedial Action Taken.* A driver drove off without disconnecting his load line which caused 30 barrels of produced water to be released. No fluids were recovered. The affected area is approximately 300' x 35'. This release occurred on location and flowed west off location.													
Describe Area Affected and Cleanup Action Taken.* Talon/LPE was contracted to perform remedial activities for this release. The impacted area was subsequently excavated to a depth of 1-feet deep. The contaminated soil was disposed of at Lea Land, LLC. The area was re-contoured to match the surrounding location. The lab results are attached along with a site map. The soil testing results are under the Recommended Remedial Action Levels (RRAL's). No further actions are required.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature: Chris Jones							OIL CONSERVATION DIVISION						
						Approved by Environmental Specialist:							
Title: HES Specialist						Approval Date: 9/23/2014 Expiration			Date: NA				
E-mail Addre	-mail Address: Christopher.Jones@oxy.com					Conditions of Approval:				Attached			
Date: 9/18/2	Date: 9/18/2014 Phone: 575-628-4121					FINAL				and data over distributions of the			

* Attach Additional Sheets If Necessary