

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/20/2014

NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Cypress 28 Federal #3H	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-38287	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	28	23S	29E	435	North	60	West	Eddy

Latitude N 32.28206° **Longitude** W 103.99796°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	140 bbls	Volume Recovered	130 bbls
Source of Release	Power failure on a transfer pump caused tank to overflow	Date and Hour of Occurrence	04/11/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen, James Amose-BLM		
By Whom?	Chancey Summers	Date and Hour	04/12/2013 @ 8:18 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Power failure on a transfer pump caused a tank to overflow and leak 140 bbls of oil on the ground. 130 bbls of oil were recovered via vacuum truck and power was restored to the pump.

Describe Area Affected and Cleanup Action Taken.*

Power failure on a transfer pump caused a tank to overflow and leak 140 bbls of oil on the ground. 130 bbls of oil were recovered via vacuum truck and power was restored to the pump. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 01/09/2014 and approved by Jennifer Van Curen of the BLM via email on 01/30/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by District Supervisor:		
Title: HES Advisor	Approval Date: 10/24/2014	Expiration Date: NA	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10-10-14 Phone: (575) 397-8216	FINAL		

* Attach Additional Sheets If Necessary

2RP-1639