

Received 5/26/2015

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: OXY USA WTP Limited Partnership	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: Winston SWD #4	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No.: Lease #: 30-015-30337
------------------------	------------------------	--------------------------------

LOCATION OF RELEASE

Unit Letter E	Section 31	Township 21S	Range 24E	Feet from the 1535'	North/South Line North	Feet from the 660'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.43826 N Longitude -104.54515 W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 bbl	Volume Recovered: 15 bbls
Source of Release: Bull Plug Broke	Date and Hour of Occurrence 2/26/15	Date and Hour of Discovery 2/26/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The bull plug broke on the discharge line of the reda pump causing a release of 30 barrels of produced water. The facility was shut-in, the plug was replaced and the facility was put back into service. A vacuum truck was immediately called to the location and 15 barrels of produced water were recovered. Talon/LPE was contracted to perform an initial site assessment and soil sampling.

Describe Area Affected and Cleanup Action Taken.* The majority of the spill remained in the steel building under the equipment. However the berm was breached on the east side of the facility. Talon/LPE performed soil sampling within the impacted area. Upon receipt of analytical results from the soil sampling activities Talon/LPE drafted a work plan that was subsequently approved by NMOCD & BLM. Talon/LPE performed the work to the specifications laid out in the work plan, collected confirmation soil samples, and backfilled the excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.co m, c=US Date: 2015.05.26 11:47:08 -05'00'	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: _____ ACCEPTED FOR RECORD NMOCD HMP	
Printed Name: Chris Jones	Approval Date: N/A	Expiration Date: N/A
Title: HES Specialist	Conditions of Approval:	
E-mail Address: Christopher.Jones@oxy.com	Attached <input type="checkbox"/>	
Date: 5/13/2015 Phone: 575-628-4121	Due to equipment, some contamination left in place. Clean up deferred until site abanondoment	

* Attach Additional Sheets If Necessary

2RP-2870