District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action												
						<b>OPERA</b>	ΓOR		☐ Initi	al Report	$\boxtimes$	Final Report
		lewbourne C		Contact: Zack Thomas								
		0 Hobbs, NN		Telephone No. 575-602-2188 Facility Type: Producing Oil Well								
Facility Name: Malaga 30 Fed Com #1H												
Surface Ow	ner: State	wner: S	r: State of NM API No: 30-015-40287									
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County												
Unit Letter I						South Line South	Feet from the 350'	East/West Line East		County Eddy		
LatitudeLongitude												
NATURE OF RELEASE												
Type of Rele Source of Re			Volume of Release: 230 bbls Volume Recovered: 200 bbls									
Source of Re	lease: On v		Date and Hour of Occurrence Date and Hour of Discovery 1-16-13									
Was Immedia	ate Notice (	equired	If YES, To Whom?									
By Whom? Z			Date and Hour: 4-25-13 4:00 PM									
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*									RE	CEIV	ED	7
MAY 01 2013												
NMOOD 477												
Well service rig was tripping in hole with tbg when well kicked off flowing up tbg. Crew immediately picked up TIW safety valve & stabbed onto tbg & SWI. A plug was then set in tbg via slick line truck. Tbg was then blown down to production tanks & the crew finished RIH w/ tbg operations. RDMO												
well servicing rig. An estimated two bbls oil were dispersed into air during blowout.												
Describe Area Affected and Cleanup Action Taken.*												
Areas affected by blowout were the location itself & lease road & pasture off the south side of location. OCD does not require any remedial action at this time based on analytical data.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
		ddition, NMC ws and/or regu		otance of a C-141	report de	oes not reliev	e the operator of	respons	ibility for c	ompliance v	vith any	other
reactur, state,	or rocur in		OIL CONSERVATION DIVISION									
Signature:	Boule-	1										
	^ /		Approved by Environmental Specialist:									
Printed Name	e: Zack Tho		a/2/11.									
Title: Environmental Rep.						Approval Dat	e: 4/4/0		Expiration	Date: N	1/4	
E-mail Addre	ess: zthomas	(	Conditions of Approval:  Attached									
Date: 4-26-13				one: 575-602-218		tru	人		12RF	2-1	569	
Attach Additional Sheets If Necessary Sauples taben as diverted by OCD stat												
					111	. 100	ىكى ھار	en	0	K to	1	pre