

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-JV-CVX-BS #026H; 2RP #3745	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 30-015-42375
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 23	Township 24S	Range 30E	Feet from the 100	North/South Line North	Feet from the 1040	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.210419° Longitude: W 103.846107°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 16 bbls oil 15 bbls produce water	Volume Recovered: 10 bbls oil 10 bbls produced water
Source of Release: stuffing box	Date and Hour of Occurrence: 6-15-16 @ 7:00am	Date and Hour of Discovery: 6-15-16 @ 7:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson via Email	
By Whom? Bradley Blevins	Date and Hour: 6-15-16 @ 1:58 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*


Packing failed in the stuffing box releasing fluid to ground surface surrounding the wellhead. A vacuum truck was called to the location to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Packing failed in the stuffing box releasing fluid to ground surface surrounding the wellhead. A vacuum truck was called to the location to recover the standing fluid. All fluid remained on the well pad. Contaminated soil was excavated and hauled to a state approved disposal facility and samples were collected. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: Bradley Blevins	Approval Date: 12/1/2016	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	FINAL	Attached <input type="checkbox"/>
Date: 10-25-16 Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

2RP-3745