

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1630554955

**OPERATOR**
 Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: ELECTRA FEDERAL #058	Facility Type: Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38182
------------------------	------------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	10	17S	30E	580	North	1650	West	Eddy

32.8547325,-103.963089

### NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls of Oil ; 5 bbls of PW	Volume Recovered: 4 bbls of Oil ; 4 bbls of PW
Source of Release: Stuffing Box Leak	Date and Hour of Occurrence: 10/21/2016 unknown	Date and Hour of Discovery: 10/21/2016 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a failed packing in the stuffing box. The packing was removed and a new packing installed. Vacuum trucks were immediately dispatched to recover all standing fluid from the well pad. The impacted area of the well pad was lightly scraped to remove the surface impact and the impacted soil was hauled off.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred on the well pad location surrounding the well. There was no impact to the pasture. Concho had the spill site sampled to delineate any possible impact from the release and presented a remediation work plan to the NMOCD and BLM for approval prior to any significant remediation work. All work has been completed according to the workplan approved by the NMOCD and BLM on April 18, 2017 and April 3, 2017 respectively.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 11/2/17	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: Like Approval BLM Attached <input type="checkbox"/>	
Date: 10/24/2017	Phone: 575-746-2010	

\* Attach Additional Sheets If Necessary

2RP-3969