

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAB1900944059
District RP	2RP-5159
Facility ID	
Application ID	pAB1900940510

Release Notification

Responsible Party

Responsible Party: Percussion Petroleum Operating, LLC	OGRID 371755
Contact Name: Jerry Mathews	Contact Telephone: 575-748-5234
Contact email: Jerry@percussionpetroleum.com	Incident # (assigned by OCD) NAB1900944059
Contact mailing address 156 Rock Daisy Road Lakewood, NM 88254	

Location of Release Source

Latitude 32.60875

Longitude -104.46619

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Huber Federal #3H	Site Type: Federal
Date Release Discovered: 11/2/2018	API# (if applicable): 30-015-38163

Unit Letter	Section	Township	Range	County
A	3	20S	25E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☒ Crude Oil	Volume Released (bbls): 250bbls	Volume Recovered (bbls): 165bbls
☐ Produced Water	Volume Released (bbls):	Volume Recovered (bbls):
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☒ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: The production battery on the location of the subject well experienced a spill during the morning hours of November 2, 2018. A newly installed LACT unit circulated oil into a stock tank that then ran over. Estimated volume of the spill was 250bbls of crude oil. All the spilled oil remained in the containment berm surrounding the battery. The free liquid inside the berm was vacuumed up, totaling 165bbls of crude oil.

State of New Mexico
Oil Conservation Division

Incident ID	NAB1900944059
District RP	2RP-5159
Facility ID	
Application ID	pAB19009450510

Was this a major release as defined by 19.15.29.7(A) NMAC?

☒ Yes ☐ No

If YES, for what reason(s) does the responsible party consider this a major release?
>25bbls

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
Toby Rhodes to Jim Amos (BLM) by phone at 3:30 PM and Mike Bratcher (NMOCD) by email at 4:00 PM

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Michael Martin

Title: Petroleum Engineer

Signature: 

Date: 11/17/2018

email: Michael@percussionpetroleum.com

Telephone: (713) 429-4249

OCD Only

Received by: 

Date: 1/09/2019