

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD - REC'D 8/9/2020

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

Operator

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMLC065347

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit or CA/Agreement, Name and/or No.
SW93

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.
WCPN GASCOM UT2 1

2. Name of Operator

CHEVRON USA INCORPORATED

Contact: HOWIE LUCAS

E-Mail: howie.lucas@chevron.com

9. API Well No.
30-015-24024-00-S1

3a. Address

6301 DEAUVILLE BLVD
MIDLAND, TX 79706

3b. Phone No. (include area code)

Ph: 432-487-7216

10. Field and Pool or Exploratory Area
WHITE CITY-WOLFCAMP

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 20 T24S R26E NESW

11. County or Parish, State

EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

06/25/2020 MIRU. Test casing to 1,000 psi for 15 minutes successfully.

06/26/2020 Cut tubing at 9,757'. N/U and test BOPE. Spot LCM material.

06/29/2020 Spot LCM.

06/30/2020 Spot 60 sack class H cement: 9,740'-9,072'. Attempt to tag, tubing is stuck. Cut at 8,327', work pipe, not free.

07/01/2020 Perforate tubing at 8,327', no circulation. Perforate tubing at 8,000', circulation established. Cut tubing at 8,000', tubing free. Spot 75 sacks Class H cement: 8,000'-7,665'.

07/02/2020 Tag TOC at 7,645'. Spot MLF. Spot 40 sacks Class C cement: 5,220'-5,021'. Perforate casing at 3,590' and establish injection 3 BPM at 750 psi. Squeeze 55 sacks Class C cement: 3,590'-3,425'.

07/06/2020 Tag TOC at 3,374'. Failed bubble test in surface casing. Pressure test production casing to 1,000 psi for 15 minutes successfully. Perforate casing at 2,560'. Squeeze 295 sacks Class C

RECLAMATION PROCEDURE
ATTACHEDRECLAMATION
DUE 1-16-21

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #522652 verified by the BLM Well Information System
For CHEVRON USA INCORPORATED, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 07/23/2020 (20PP1936SE)

Name (Printed/Typed) HOWIE LUCAS

Title WELL ABANDONMENT ENGINEER

Signature

(Electronic Submission)

Date 07/22/2020

gc 8/11/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Accepted for record - NMOCD

Approved By

Title


Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #522652 that would not fit on the form

32. Additional remarks, continued

cement: 2,560?-1,691?.

07/07/2020 Tag TOC at 1,698'. Bubble test passed. Perforate casing at 1,697?, full circulation established. RDMO P&A equipment to allow verification of passed bubble test.

07/16/2020 MIRU rig-less cement equipment. Circulate annulus clean. Squeeze 665 sacks Class C cement: 1,698?-surface. Verified cement to surface. RDMO. P&A complete.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMLC065347

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

8. Well Name and No.
White City Penn Gas Com 2 1

2. Name of Operator
Chevron USA Incorporated

Contact: **Howie Lucas**
E-Mail: **howie.lucas@chevron.com**

9. API Well No.
30-015-24024

3a. Address
6301 Deauville Blvd., Midland, TX 79706

3b. Phone No. (include area code)
Ph: 832-588-4044

10. Field and Pool or Exploratory Area
White City Penn (GAS)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Section 20, T24S, R26E SWNE 1830FSL 1650 FWL

11. Country or Parish, State
Eddy County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

06/25/2020 MIRU. Test casing to 1,000 psi for 15 minutes successfully.

06/26/2020 Cut tubing at 9,757'. N/U and test BOPE. Spot LCM material.

06/29/2020 Spot LCM.

06/30/2020 Spot 60 sack class H cement: 9,740'-9,072'. Attempt to tag, tubing is stuck. Cut at 8,327', work pipe, not free.

07/01/2020 Perforate tubing at 8,327', no circulation. Perforate tubing at 8,000', circulation established. Cut tubing at 8,00', tubing free. Spot 75 sacks Class H cement: 8,000'-7,665'.

07/02/2020 Tag TOC at 7,645'. Spot MLF. Spot 40 sacks Class C cement: 5,220'-5,021'. Perforate casing at 3,590' and establish injection 3 BPM at 750 psi. Squeeze 55 sacks Class C cement: 3,590'-3,425'.

07/06/2020 Tag TOC at 3,374'. Failed bubble test in surface casing. Pressure test production casing to 1,000 psi for 15 minutes successfully. Perforate casing at 2,560'. Squeeze 295 sacks Class C cement: 2,560'-1,691'.

07/07/2020 Tag TOC at 1,698'. Bubble test passed. Perforate casing at 1,697', full circulation established. RDMO P&A equipment to allow verification of passed bubble test.

07/16/2020 MIRU rig-less cement equipment. Circulate annulus clean. Squeeze 665 sacks Class C cement: 1,698'-surface. Verified cement to surface. RDMO. P&A complete.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Howie Lucas

E-mail address: **howie.lucas@chevron.com**

Title **Well Abandonment Engineer, Attorney in Fact**

Signature



Date **07/21/2020**

THE SPACE FOR FEDERAL OR STATE OFFICE USE

3/6



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm

TAKE PRIDE
IN AMERICA

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (**Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure**). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

4/16

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Petroleum Engineering Tech
575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias
Environmental Protection Specialist
575-234-6230


Crisha Morgan
Environmental Protection Specialist
575-234-5987

Melissa Horn
Environmental Protection Specialist
575-234-5951

Kelsey Wade
Environmental Protection Specialist
575-234-2220

Trishia Bad Bear, Hobbs Field Station
Natural Resource Specialist
575-393-3612

5/5



UNI
DEPARTMENT
BUREAU OF L

CARLSBAD FIELD OFFICE
620 EAST GREENE STREET
CARLSBAD, NEW MEXICO 88220

OFFICIAL USE

PENALTY FOR PRIVATE USE \$300

Hasler
07/28/2020
FIR

US POSTAGE \$0C



2
011

Permitting Jean

-35-

CHEVRON USA INC
6301 DEAUVILLE BLVD
MIDLAND TX 79706