Submit 1 Copy To A	Appropriate District		State of N	ew Mexico	OCD – RE	EC'D 9/10/2020	Form C-103	
Office <u>District I</u> – (575) 393-6161		Energy, Minerals and Natural Resources			Resources	WELL API NO.	Revised July 18, 2013	
1625 N. French Dr., <u>District II</u> – (575) 74		OIL CONCEDIVATION DIVICION				WELL API NO.	30-015-47278	
811 S. First St., Arto District III – (505) 3		OIL CONSERVATION DIVISION 1220 South St. Francis Dr.				5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410			Santa Fe, NM 87505			STATE 6. State Oil & G	FEE X	
1220 S. St. Francis Dr., Santa Fe, NM						o. State on & o	as Lease 110.	
87505	SUNDRY NO	7. Lease Name or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						Beagle 35-34-22-27 Fee		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other						8. Well Number	10211	
Name of Operator WPX Energy Permian, LLC						9. OGRID Number 246289		
3. Address of Operator						10. Pool name or Wildcat		
3500 One Williams Center, Tulsa, OK 74172 4. Well Location						Purple Sage; W	/olcamp (Gas)	
4. Well Localid	ъ	: 1076 feet	from the	South	line and 63	38 feet fro	om the <u>East</u> line	
Section			vnship 228		27E	NMPM	County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)								
	12. Check	x Appropriate E	ox to Indi	icate Natur	e of Notice,	Report or Other	: Data	
	NOTICE OF		· · ·	I	CLID	SEQUENT RE	DOPT OF:	
NOTICE OF INTENTION TO: SUBS							ALTERING CASING	
TEMPORARILY		CHANGE PL				ILLING OPNS.	P AND A	
PULL OR ALTE DOWNHOLE CO	_	☐ MULTIPLE C ☐	OMPL	CA	SING/CEMEN	T JOB 📙		
CLOSED-LOOP								
OTHER: OTHER:								
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
proposed completion or recompletion.								
Our planned pilot hole was not noted in the Comments section of our permit application. See attached for details on pilot hole and cement plug.								
cement p	iug.							
Spud Date:			Dia Da	lease Date:				
Spud Date.			Kig Ke	lease Date.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
_								
SIGNATURE_ ¿	Danes Tho	mpn	TITLE	Regulatory	Technician	D	ATE_09/10/2020	
Type or print nan	ne Dana Thomp	son	E-mail	l address: da	na.thompson@	wpxenergy.com pp	HONE: <u>539-573-3588</u>	
For State Use Only								
APPROVED BY: TITLE District III Geologist DATE 9/23/2020							ATE 9/23/2020	
Conditions of Ap								

Beagle 35-34-22-27 Fee 402H

	8-3/4" Setting Balanced Cement Plug							
	Objective: The objective is to set a 500' balanced plug to plug back the pilot and provide a kickoff 8733' point to drill the curve for a lower wolfcamp Y sand							
1	P/U muleshoe, 2-7/8" stinger, and 2-7/8" x 5" S-135 4-½" IF XO a. Verify stinger and XO have been drifted before RIH							
2	b. Verify muleshoe sub is ported around OD TIH to 10160' to set viscous pill. Circulate bottoms up through chokes at 10160' a. Verify kelly down for space-out when we pick up out of pill							
3	Verify BBL IN/OUT while spotting viscous-weighted pill and cement plug in following steps							
4	Pump 10 bbls of viscous-weighted pill ~ 80 visc from slugging pit and displace with 167.65 bbls of mud							
5	P/U out of the pill 50-ft, this will place the bottom of the stinger at 8,983' which should be the top of the pill.							
6	Rig up cementers, test lines to 5,000 psi, and pump job as follows: a. Pump 20 bbls fresh water spacer b. Mix and pump 309 sks, 17.5 ppg, 0.9372 ft3/sk Class H cement @ 3-4 bpm i. Monitor pressure closely as cement approaches and passes through drillpipe float c. Displace with 1.28 bbls of FW followed by 142.64 bbls mud from active @ 3-4 bpm i. NOTE: Slow down pumps to 2 bpm at 138.64 bbls displaced and pump last 4 bbls of displacement at 2 bpm ii. NOTE: Total displacement is 142.64 bbls							
7	Pull 10 stands at 2 min/stand to place end of stinger at approximately 8,003' (480' above TOC)							
8	Circulate while full rate rotating and reciprocating pipe verifying drillpipe, stinger, and backside are clear of cement							
9	Discuss plan forward with entire team after circulating at least two bottoms up.							
10	WOC 24 Hrs before dressing plug							

