	To Appropriate Distric	:t	State of New Mexico			Form C-103	
Office District I – (575		•	Minerals and Nat	ural Resources	Revised August 1, 2011 WELL API NO.		
1625 N French <u>District II</u> – (57)	Dr , Hobbs, NM 8824 5) 748-1283		OIL CONSERVATION DIVISION			30-015-20685	
611 5 First St., Artesia, NW 66210			20 South St. Francis Dr.		5. Indicate Type of		
1000 Rio Brazo	Rio Brazos Rd, Aztec, NM 87410 Sonto Eq. NIM 97505				STATE State Oil & Gas I	FEE	
1220 S St Fran	District IV – (505) 476-3460 Salita Fe, INIVI 87303 1220 S St Francis Dr, Santa Fe, NM 87505				307561		
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name or U	nit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					EMPIRE SOL	TH DEEP UNIT	
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other					8. Well Number	3	
2. Name of Operator					9. OGRID Number		
THREE RIVERS OPERATING COMPANY, LLC						2295	
3. Address of Operator 1122 S. CAPITAL OF TX HWY, SUITE 325, AUSTIN, TX 78746					10. Pool name or Wildcat EMPIRE SOUTH (WOLFCAMP)		
4. Well Location							
Uni	t LetterN	:660fee	from the _SOUTH	line and	feet from	theWESTline	
Sec	tion 31		ownship 17S	Range 29E	NMPM	County EDDY	
			n (Show whether DI	R, RKB, RT, GR, etc	e.)		
3646 GL							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING						JRT OF: LTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A							
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB							
DOWNHOLE OTHER:	E COMMINGLE			OTHER.		П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of							
prop	osed completion o	r recompletion.					
Plug back from	m Morrow perfs 10	0,711'-10,830' & 1	ecomplete in Wolfca	amp perfs 8,601'-8,	604'.		
Procedure:							
1. Prepare location, test anchors, move in 500 bbl steel frac tank							
2 MIRTI: pump brine down that to kill well							
3. NU BOP; release pkr & pul 700% & scanalog out of hole RECEIVED							
4. RIH w/bit & scraper to 10,700' & circulate with KCL water 5. Rig up wireline; set CIBP @ 10,630'; dump bail 35' cmt AUG 11 2011							
6. Pressure up on casing to 1000#; run CBL-GR-CCL from PBTD to TOC est 5,700'							
7. Perforate 8,601-8,604' w/ 2 spf 8. RIH w/ 2 3/8" tbg & pkr w/ tailjoint & on-off tool [NMOCD ARTESIA]							
9. Set pkr @ 8,550'; pressure up to 500# on backside							
10. Swab well down; spot 500 gals 15% HCL Petrol 10 down tbg; displace w/ KCL; pump acid @ slow rate							
11. Swab well into test for production, larger treatment							
12. Release pkr & pull tbg OOH 13. RIH w/ tbg & production BHA; set TAC 3 jts above S.N.							
13. RIH w/ tog & production BHA; set TAC 3 jts above S.N. 14. RIH w/ rods & pump 15. Set pumping unit w/gas engine 16. Return well to production 16. Return well to production							
	umping unit w/gas				for t	N.C. File a	
16. Retui	rn well to producti	on			C-101	1. C-10 2 to	
Spud Date:			Rig Release D	ate:		1, C-10 2 to recomplete to	
•	08/26	/2011			09/05/2011	new zone.	
			J				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE							
Type or print name TOM STRATTON E-mail address: tstratton@3rnr.com PHONE: 512-706-9849							

Conditions of Approval (if any): 626-0843

WELL: EMPIRE SDU 3 (3 RIVERS) CURRENT WELLBORE SCHEMATIC

FIELD: SOUTH EMPIRE-MORROW GAS
COUNTY / STATE: EDDY / NEW MEXICO

LOCATION: 1,980.0 FWL & 660.0 FSL OF THE SVY, SEC 31, A-

ELEVATION: 3,651.00 GR 3,670.00 RKB

PN: 890427 Chesapeake API: 3001520685 SPUD DATE: 8/5/1972 RIG RELEASE: FIRST SALES: 12/1/1972

