OCD-ARTESIA

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No 1004-0137 Expires Maich 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NM-LC061497

6 If Indian, Allottee or Tribe Name

5 Lease Serial No

abandoned we	ell. Use Form 3160-3 (A	APD) for such pro	posals.				
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7 If Unit or CA/Agreement, Name and/or No 8 Well Name and No. Gulf Federal #3 9 API Well No		
I Type of Well ☐ ☐ Gas Well ☐ ☐ Other							
2. Name of Operator Chevron USA Inc.							
3a. Address 15 Smith Rd., Midland, TX 79705 (Attention Anthony Zenos)		3b Phone No (include area code) 432-561-8600		30-015-25265 10 Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Sec., T., R., M., or Survey Description) UL C, Sec. 13-T26S-R29E 572' FNL & 1715' FWL					Brushy Draw Delaware 11 County or Parish, State Eddy, New Mexico		
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent ✓ Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction ✓ Plug and Abandon Plug Back	Production (Standard Reclamation Recomplete Temporarily At Water Disposal	ŕ	Water Shut-Off Well Integrity Other		
					rk and approximate duration thereof s of all pertinent markers and zones		

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. Notify NM-BLM on 8-15-11 - Shirley

2. Spot 150 sx "c" cmt from 5204'-5000' woc. Tag @ 4837'

3. Displace hole w/115 bls MLF

4. Perf 4 holes @ 3250' Press up to 1500 PSI Perf 4 holes @ 2750' Press up to 1500 PSI

5. Spot 100 sx "c" cmt from 3307'-2320' woc tag @ 2391'

6. Perf 4 holes @ 800' circ 215 sx "c" cmt down 5 1/2" up through 8 5/8" annullus csg to surf woc tag @ surf

7. Install Dry hole marker P&A complete 8-19-11

RECEIVED

SEP 12 2011

NMOCD ARTESIA

RECLAMATION DUE 2-15-12

Accepted as to plugging of the well bore.

iability under bond is retained until

orface restoration is completed.

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)								
Jimmy Bagley	Title Manager							
Signature	Date 8/19/2011	ACCI	EPTED	FOR REC	ORD			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by .	Title		DateSEP	5 2011				
Conditions of approval, if any, are attached Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject lear which would entitle the applicant to conduct operations thereon	ose Office	611	A CA	AND MANAGEN	MENT			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully states any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.								
(1 /								

(Instructions on page 2)

Al 9/13/2011

Accepted for record NMOCD

