

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410.
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-31381

Release Notification and Corrective Action

NMLB 1128636288

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-748-5238
Facility Name Cotton Draw #89		Facility Type Gas Well
Surface Owner	Mineral Owner	Lease No.

LOCATION OF RELEASE


Unit Letter	Section 3	Township 25S	Range 31E	Feet from the 250	North/South Line South	Feet from the 1980	East/West Line East	County Eddy County
-------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	-----------------------

NATURE OF RELEASE

Type of Release Condensate	Volume of Release 28 BBLs	Volume Recovered 6 BBLs
Source of Release Lightening Struck Produced Water Tank	Date and Hour of Occurrence 9-20-11 11:30 PM	Date and Hour of Discovery 9-20-11 11:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (OCD) Kent Cassell (BLM)	
By Whom? Merle Lewis	Date and Hour 9-21-11 11:47 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Lightening struck the battery destroying the fiberglass produced water tank and associated piping. It resulted in a release of 28 bbls of condensate on location. We were able to recover 6 bbls of condensate. The rest was burned in the explosion.

Describe Area Affected and Cleanup Action Taken.*

The well was immediately shut in, the spill was contained in the dike area 20'x 40' the area was stained but nothing standing. Will remove burned equipment and will now convert this location to a SWD well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Adrienne Verkler		OIL CONSERVATION DIVISION	
Printed Name: Adrienne Verkler		Approved by <u>[Signature]</u> District Supervisor	
Title: Field Tech II		Approval Date: OCT 13 2011	
Date: Sept. 26, 2011 Phone: (575) 748-0174		Expiration Date:	
Attach Additional Sheets If Necessary		Conditions of Approval: Attached <input type="checkbox"/>	

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

11/13/2011

2 RP-912