Test in Northwest	New Mexico			MEXICO PAG		7A A	10-12	78	7
Operator A	tes let	edeum (or	Cyc.	Well API # 30 - 0 Well Name & No. AL					
Location Of W	ell: Unit	Section	<sup>1</sup> 33	_ Township	95	Range _		Count	
	Name	of Reservoir or Poo	ĺ	Type of Prod. (Oil or Gas)	Method (Flow A		Prod. Med (Tbg. Or C		Choke Size
Upper Completion	wolf	Amp		GAS	Fla	سربه	G+5		13/64
Lower Completion	ORdo	VICAN		GAS	ART	27	169.		24/64
			FLO	Ŵ TEST NO.	1				7
		late): <u>/3:45</u>					Upper	<del></del>	Lower
		1:00 pm /c					Complet	ion	Completion
• • •		ucing						<u>.</u>	228
ressure at begi	nning of test		TRI	FOEIV	En	······································	<u>/3C</u>	<u>ر</u>	220
									YES
Aaximum press	ure during tes	t	·	IAN <b>04</b> -28	12		140	)	500
Ainimum pressi	ure during test	t	KINAC	100 ADT		• • • • • • • • • • • • • • • • • • • •	/30	<u> </u>	230
ressure at conc	lusion of test.		TAME	JOD ART	ESIA	• • • • • • • • • • • • • • • • • • • •	<i>13</i> 0	_	370
		/aximum minus Mir					_		780
Vas pressure ch	ange an increa	ase or a decrease?		т	tal Tima (	······································	JACPE	12	Juck 200
Vell closed at (I	hour, date): <u>/</u>	10:00 12-	8-11	Pro	oduction_	<u>"21</u>	HRS		
AN T LOGGERION		bbls; Grav.		Uas I IUuu		-	MCF; GOR	ļ!	NA
				_					7
		16): <u>10;28</u> 10:15 12	12 -8- 12 -8-				Upper Completic		Lower Completion
	_	cing						_	
ressure at begin	ning of test						<u>/30</u>	_	<u> 370</u>
tabilized? (Yes	or No)	· · · · · · · · · · · · · · · · · · ·	• • • • • • • • • • • • • • • • • • • •				. YES	_	YES
aximum pressu	re during test.						290	<u>.</u>	4/0
linimum pressu	re during test.						. <u>130</u>	)	120
ressure at concl	usion of test	• • • • • • • • • • • • • • • • • • • •					. 270	)	210
essure change	during test (M	aximum minus Min	imum)				160		290
		se or a decrease?				<i>-</i>		ر بجع	DECRES
	_	7:30 12-9-		Tot	al Time O	1 ~23	HRS	15	min,
il Production uring Test:		_bbls; Grav		Gas Produc	tion .		MCF; GOR		N/4
			·						_
_									
emarks:									
emarks:		ation herein containe	d is true a	and complete to	the best o	, ,	<b>`</b>		1 -
emarks:nereby certify the	at the informa			and complete to		, ,	wledge.	~ (	1p.
emarks:nereby certify the	at the informa	ation herein containe	d is true a	and complete to  Oper	ator XA7	Zes f	Haden	n (	Sp.
emarks:  hereby certify the oproved  New M	at the informa	ation herein containe	d is true a	2 Open By _	ator XA7	zs fa Leck supen	stacken	zeh	IF. Aice N

منبغ م