OCD-ARTESIA

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No 1004-0137
Expires March 31, 2007

5 Lease Senal No. 109644


SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to abandoned well. Use Form 3160-3 (AF	6 If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE- Other instruc	7 If Unit or CA/Agreement, Name and/or No.				
1 Type of Well Oil Well O Gas Well O Other			8 Well Name and No.		
2 Name of Operator Beach Exploration, Inc.	·		9. API Well No	LONESOME UNIT#	27
3a Address 3 800 N. Marienfeld, Suite 200, Midland, TX 79701	3b Phone No (include 432 683 6226	area code)	30-015-25495 10 Field and Pool, or Exploratory Area		
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)			W. HIGH LONESOME QUEEN		
1,650 FNL, 330 FWL, Sec 20, Unit E ,T 16 S, R 29 E			11 County or Parish, State EDDY COUNTY, NM		
12. CHECK APPROPRIATE BOX(ES) TO IN	NDICATE NATUR	E OF NOTICE, R	EPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION		E OF ACTION	,		
Acidize Acidize Alter Casing Subsequent Report Acidize Casing Repair	Deepen Fracture Treat New Construction	Production (Standarding Reclamation Recomplete		ater Shut-Off ell Integrity her	
Final Abandonment Notice Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporanly Al Water Disposal	oandon		
testing has been completed Final Abandonment Notices shall be file determined that the site is ready for final inspection.) The WHL #27 injector failed a mechanical integrity test or psi during the test. The casing pressured to 300 psi and the have integrity but the casing has a leak. The well is current Procedure: 1 Connect tubing to central battery with poly line and flow 2 RU pulling unit. NU BOP. Release packer. Pull packer 3 Pick up 5 1/2" bridge plug, packer and 2 3/8" workstrin 4 Work packer up hole testing tubing and backside to loca 5 Spot a 25sx balanced cement plug as follows: pump 7.5sx 6 Pull up 12 jts, pump 6 BFW, set packer and hesitation so 7 POOH w/tubing. RU reverse unit. Pickup 4 3/4" bit, dr 8 Drill out 5 1/2" BP at 1700' and clean out hole below per 9 RIH w/2 3/8" x 5 1/2" PC AD-1 tension packer, PC SN a 10 Conduct OCD witnessed MIT. Return well to injection	n 2/21/12 conducted ten slowly bled to 0 partly shut-in pending we back to reduce pregrand Duo-10 tubing g. RIH and set BP attecasing leak. RIH accept casing leak. The conduction of the conduc	by Richard Inge (Nosi. With these indice repair. Wellbore dessure. and stand back. In 1700'. Pull up, set w/12 jts tailpipe and the common the common that it would be string. Drill out squent proof the common that it would be string. Drill out squent proof the common that it would be string. Drill out squent proof the common that it would be string.	M OCD). The tubing tations, we suspect the lagram attached. packer and test BP of d packer to casing legists and, and 7.5sx (eeze plug and pressure) laydown drill collar	g pressure stayed at 1, nat the tubing and pack to 2000 psi. ak. C-neat are test casing. s and workstring. and set packer at 1717'.	ker
Name (Printed/Typed), Jack M. Rose	Title E	ngineer		Accepted for	Or rocar
Signature Management of the state of the sta	Date)3/02/2012	NMO	SILIBCON CDX (
THIS SPACE FOR FE	DERAL OR S	TATE OFFICE	USE		Tenpa
Approved by /s/ JD Whitlock Jr Conditions of approval, if any, are attached Approval of this notice doc certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a cr. States any false, fictitious or fraudulent statements or representations as	es not warrant or he subject lease	ffice CFO	Date to make to any depart	8/19/12 Herese W	

(Instructions on page 2)

SEE ATTACHED FOR CONDITIONS OF APPROVAL

MAR 2 0 2012 NMOÇD ARTESIA



Conditions of Approval

Beach Exploration, Inc. West High Lonesome Unit - 027 API 3001525495

March 9, 2012

- 1. Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
- 2. Provide a cement bond log record from plug back total depth to top of cement and a cement bond log record subsequent to the planned cement squeeze.
- 3. Surface disturbance beyond the existing pad must have prior approval.
- 4. Casing added or replaced requires a prior notice of intent (BLM Form 3160-5) approval of the design.
- 5. Closed loop system required. 2000 2M BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 (attachment 1, 2M diagrams of choke manifold equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 6. Workover approval is good for 90 days (completion to be within 90 days of approval).

Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
 - a) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with 200 psig differentials between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
 - b) Document the pressure test on a calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
 - c) At least 24 hours before the test: In Eddy County email Paul R. Swartz <u>pswartz@blm.gov</u>, (phone 575-200-7902). If there is no response phone 575-361-2822. Note the contact notification method, time, & date in your subsequent report.
 - d) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
 - e) Use of tubing internal protection, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer is required. The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
 - f) Submit the original subsequent sundry with three copies to BLM Carlsbad.

- 2) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization.
 - a) Approved injection pressure compliance is required.
 - b) If injection pressure exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.
 - c) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum.
 - i) Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 3) Other unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 4) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity.
- 5) The annulus is to be maintained full of packer fluid at atmospheric pressure. Installation of equipment that will display on site, continuous open to the air fluid level is required. A BLM inspector may request verification of this fluid level at any time.
- 6) **Submit a subsequent report (Sundry Form 3160-5)** describing the installation of packer fluid level monitoring equipment within 30 days of beginning injection.
- 7) The operator shall keep monthly records documenting that the casing annulus is fluid filled. A suggested format for these records is available from the BLM Carlsbad Field Office. Copies of those records shall be furnished at the request of a BLM authorized officer.
- 8) Loss of packer fluid above five barrels per month requires notification of the BLM authorized officer within 5 days.
- 9) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of Opsia. Notify the BLM's authorized officer ("Paul R. Swartz" pswartz@blm.gov>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 10) Also submit to this office a (Sundry Form 3160-5) Notice of Intent (NOI) for planned well work involving a formation change, casing repair/replacement, and injection well fracture treatment for approval by BLM and NMOCD. Verbal approval for the plan may be given by a BLM authorized officer, with the NOI filed within five business days. Packer and tubing repair (normal maintance procedures) do not require a NOI, but a subsequent sundry needs to be filed. http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html (see CFR § 3162.3-2 43 & CFR § 3160.0-9 (c)(1)).
 - a) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of required equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer is required. The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.