Submit I Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District</u> I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-015-39406
811 S. First St., Artesia, NM 88210		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.	STATE STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr., Santa Fe, NM		
87505	ICEC AND DEPONTS ON WELLS	7 Y N Y Y Y Y
	ICES AND REPORTS ON WELLS  SSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	ARABIAN 6 FEE
PROPOSALS.)		8. Well Number 2H
1. Type of Well: Oil Well	Gas Well Other	
2. Name of Operator		9. OGRID Number
	COG Operating, LLC	229137
3. Address of Operator		10. Pool name or Wildcat
550 W. Texas A	Ave., Suite 100, Midland, TX 79701	Penasco Draw;SA-Yeso (Assoc)
4. Well Location		
Unit Letter N :	150 feet from the South line and 170	0 feet from the West line
Section 6	Township 19S Range 26E	NMPM County Eddy
	11. Elevation (Show whether DR, RKB, RT, GR,	elc.)
and the second s	3373' GR	According to the second of the
12. Check	Appropriate Box to Indicate Nature of Noti	ice, Report or Other Data
	•	UBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON  REMEDIAL V	<del>-</del>
TEMPORARILY ABANDON 🔲	CHANGE PLANS	DRILLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING	MULTIPLE COMPL   CASING/CEN	MENT JOB
DOWNHOLE COMMINGLE		
	i	
OTHER: CHANGE CASING PROC		
		s, and give pertinent dates, including estimated date
13. Describe proposed or composed of starting any proposed w	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple	
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple	
13. Describe proposed or composed of starting any proposed w	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple	
13. Describe proposed or composed of starting any proposed w	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple	
Describe proposed or composed or starting any proposed we proposed completion or recomposed completion.	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	Completions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or recomposed	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce	e Completions: Attach wellbore diagram of ement to surface. Drill a 8 ¾" hole to 2273' MD
of starting any proposed we proposed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce' MD. Drill a 7 7/8" lateral to new BHL @ 2750' T	e Completions: Attach wellbore diagram of ement to surface. Drill a 8 ¾" hole to 2273' MD CVD 7341' MD. Run a tapered string with 7" 26#
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	e Completions: Attach wellbore diagram of ement to surface. Drill a 8 ¾" hole to 2273' MD CVD 7341' MD. Run a tapered string with 7" 26#
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce' MD. Drill a 7 7/8" lateral to new BHL @ 2750' T	e Completions: Attach wellbore diagram of ement to surface. Drill a 8 ¾" hole to 2273' MD CVD 7341' MD. Run a tapered string with 7" 26#
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	ement to surface. Drill a 8 ¾" hole to 2273' MD TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	e Completions: Attach wellbore diagram of ement to surface. Drill a 8 ¾" hole to 2273' MD CVD 7341' MD. Run a tapered string with 7" 26#
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	ement to surface. Drill a 8 ¾" hole to 2273' MD (VD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	ement to surface. Drill a 8 ¾" hole to 2273' MD TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	ement to surface. Drill a 8 ¾" hole to 2273' MD  TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	ement to surface. Drill a 8 ¾" hole to 2273' MD  TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012
of starting any proposed we proposed completion or responsed completion or res	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce' MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.	ement to surface. Drill a 8 ¾" hole to 2273' MD (VD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.
of starting any proposed we proposed completion or responsed completion or responsed to the proposes to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½"	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' 17# L-80 casing to TD with DV/ECP Combo Tool	ement to surface. Drill a 8 ¾" hole to 2273' MD  TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012
of starting any proposed we proposed completion or responsed completion or res	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce' MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.	ement to surface. Drill a 8 ¾" hole to 2273' MD  TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012
of starting any proposed we proposed completion or responsed completion or res	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce' MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.	ement to surface. Drill a 8 ¾" hole to 2273' MD  TVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012
of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273" & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce' MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012  NMOCD ARTESIA
of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273" & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.  Rig Release Date:	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012  NMOCD ARTESIA
of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273" & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.  Rig Release Date:	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012  NMOCD ARTESIA
of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273" & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool on DV Tool and cement from 2273' to surface.  Rig Release Date:	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012  NMOCD ARTESIA
of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273" & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool en DV Tool and cement from 2273' to surface.  Rig Release Date:	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED MAY 0 2 2012 NMOCD ARTESIA
of starting any proposed we proposed completion or responsed completion or responsed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273" & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' T17# L-80 casing to TD with DV/ECP Combo Tool en DV Tool and cement from 2273' to surface.  Rig Release Date:	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED MAY 0 2 2012 NMOCD ARTESIA
13. Describe proposed or composed starting any proposed we proposed completion or responsed completion or response to drill a 12 1/4" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 1/2" Set isolation packers and ECP. Open Spud Date:	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' Tl7# L-80 casing to TD with DV/ECP Combo Tool en DV Tool and cement from 2273' to surface.  Rig Release Date:  Rig Release Date:  TITLE Permitting Tech	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED MAY 0 2 2012 NMOCD ARTESIA  Redden and belief.  DATE 5/2/2012
13. Describe proposed or compost starting any proposed we proposed completion or responsed completion or response to drill a 12 ¼" hole and kick off and drill curve to 3023 L-80 from surface to 2273' & 5 ½" Set isolation packers and ECP. Open Spud Date:  I hereby certify that the information SIGNATURE  Type or print name Kelly J. Holly For State Use Only	Pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' Tl7# L-80 casing to TD with DV/ECP Combo Tool en DV Tool and cement from 2273' to surface.  Rig Release Date:  Rig Release Date:  TITLE Permitting Tech  E-mail address: kholly@concho.com	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED  MAY 0 2 2012  NMOCD ARTESIA  PHONE: 432-685-4384
13. Describe proposed or composed starting any proposed we proposed completion or responsed completion completion or responsed completion co	pleted operations. (Clearly state all pertinent details ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.  to 1200' w/ fresh water, run 9 5/8" 36# J-55 and ce 'MD. Drill a 7 7/8" lateral to new BHL @ 2750' Tl7# L-80 casing to TD with DV/ECP Combo Tool en DV Tool and cement from 2273' to surface.  Rig Release Date:  Rig Release Date:  TITLE Permitting Tech	ement to surface. Drill a 8 ¾" hole to 2273' MD EVD 7341' MD. Run a tapered string with 7" 26# at 2273' and isolation packers in the open hole.  RECEIVED MAY 0 2 2012 NMOCD ARTESIA  Redden and belief.  DATE 5/2/2012