Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 June 19, 2008
Energy, Minerals and Natural Resources District I District II		WELL API NO. 30-015-38406	
1301 W Grand Ave , Artesia, NM 88210 OIL CO District III 12	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 District IV Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.	
1220 S St Francis Dr , Santa Fe, NM 87505		X0-0647-0405	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			7. Lease Name or Unit Agreement NameN B Tween State
1. Type of Well: Oil Well Gas Well Other:			8. Well Number 016
2. Name of Operator Apache Corporation			9. OGRID Number 873
3. Address of Operator		10. Pool name or Wildcat	
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705 4. Well Location		Artesia; Glorieta-Yeso (O) (96830)	
Unit Letter H: 1650 feet from the North line and <u>990</u> feet from the East line			
Section 25 Township 17S Range 28E NMPM County Eddy			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3684' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE			
_			
OTHER: OTHER. Including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Apache performed the following 3/21/12 MIRUSU Attempt to pull pump & tbg, both stuck. 3/22/12 RIH w/ string shot & back off tbg. POH LD tbg. 3/23/12 Ran freepoint, cut tbg below TAC & POH. 3/26/12 RIH w/ wash pipe to fish, RIH w/ overshot attempt to retrieve fish 3/27/12 RIH w/ ported sub tie on to tbg Back off tbg, POOH RIH w/wash pipe. 3/28/12 RIH w/ tbg, overshot and POOH Wash over pipe in hole. Circ hole clean 3/29/12 RIH w/ overshot attempt to jar free, POOH. Circ hole clean. 3/30/12 Attempt to retrieve fish 4/02/12 PU & RIH w/shoe, tbg, & wash pipe. Tag fish @ 4765'; Wash over fish to 5120'. Circ hole clean. 4/03/12 RIH w/ ported sub, jars, DC, & tbg. Try to release tbg. 4/04/12 RIH w/BHA. Latch on fish Freepoint & chem cut tbg. Break circ & wash over to 5402'. Circ hole clean Had scale/sand on returns			
Spud Date: 04/08/2011	Rig Release Da	ate: 04/16/2011	
I haraby partify that the information shows in	nd complete (- 4) - 1	at of mer les 1 - 1	o and heliof
I hereby certify that the information above is true a	nd complete to the be	est of my knowledg	e and bener.
SIGNATURE,	TITLE Booul	oton, Tooh	
	TITLE_Regula		DATE_06/22/2012
Type or print name Fatima Vasquez For State Use Only	E-mail address	: Fatima Vasquez@ap	achecorp com PHONE: (432) 818-1015
APPROVED BY: Made TITLE D'ST For Spewrst DATE 7/5/2012 Conditions of Approval (if any): Report tog detail : size, wt, grade, setting,			
		U	

.

N B Tween State 16 API 30-015-38406 Apache Corp.

Completion continued.

- 4/05/12 Latch on fish @ 5450'. RIH to PBTD @5660'. POOH w/ tbg & BHA. RIH w/overshot, jars, DC.
- 4/06/12 RIH w/ tbg to bottom perf @ 5306'. Pump 55 gals of WLC603 & flush w/5 BBLS 2% KCL F/W. Pump 330 gals of SRW196 Calcium Sulfate Converter w/ 20 BBLS 2% KCL F/W. Spot across perfs.
- 4/09/12 Flush w/ 1000 gals of 15% NEFE acid w/ 25 BBLS of 2% KCL F/W. RDMO Petroplex acidizing.
- 4/10/12 RIH w/ prod equip. SN @ 5301'. Pump scale inhibitor squeeze treatment.
- 4/11/12 Clean location. RDMOSU & RDMO rev unit. Start prod to N B Tween Battery.