

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1219348842
OPERATOR ☒ Initial Report ☐ Final Report
Name of Company BOPCO, L.P. *260737* Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 432-556-8730
Facility Name: Indian Flats Bass Federal #1 Tank Battery Facility Type: E&P

Surface Owner Federal Mineral Owner Federal ~~Lease No. LC-067144~~ *APX #*

Indian Flats Bass Fed #1

LOCATION OF RELEASE

30-015-24968

Unit Letter J	Section 35	Township 21S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.433905 Longitude W 104.055425

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 15 bbls	Volume Recovered: 5 bbls
Source of Release: 3" fill line to the tanks.	Date and Hour of Occurrence 6/21/12 time 1:00 p.m.	Date and Hour of Discovery 6/21/12 1:00 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Crews were installing a new heater treater at the location when a 3" line coming from the flow line header to the tanks broke. A vacuum truck was on-site removing oil from the separators and was used to recover the spilled fluid.

Describe Area Affected and Cleanup Action Taken.* The released fluid affected approximately 1500 sq. ft. inside the tank battery earthen containment. The free standing fluid was picked up with a vacuum truck.

The Site remediation for the crude oil will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor:	
Title: Waste Mgmt. & Remediation Specialist		Signed By <i>M. H. [Signature]</i>	
E-mail Address: TASavoie@BassPet.com		Approval Date: <i>11</i> 11 2012	Expiration Date:
Date: 6/24/12	Phone: 432-556-8730	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/11/12

2RP-1207

