
Forn 3160-5 (August 2007)

UNITED STATES

FORM APPROVED OMB NO 1004-0135

	BUREAU OF LAND MANA			Expires	July 31, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				5 Lease Serial No. NMNM77046		
				6. If Indian, Allottee	or Tribe Name	
SUBMIT IN TR	IPLICATE - Other instru	ctions on reverse side.		7. If Unit or CA/Agre	eement, Name and/or No.	
1. Type of Well			1	8 Well Name and No		
				N PURE GOLD 8 FED 2		
DEVON ENERGY PRODUCT	rawford@dvn.com)	30-015-27597-00-S1			
3a Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102		3b Phone No (include area code) Ph: 405-552-4524	5-552-4524 LOS M		r Exploratory S	
4 Location of Well (Footage, Sec.,	n)		11 County or Parish, and State			
Sec 8 T23S R31E NESE 198		EDDY COUNTY, NM				
12. CHECK APP	ROPRIATE BOX(ES) T	O INDICATE NATURE OF N	OTICE, REF	ORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent	☐ Acidize	Deepen	□ Production	n (Start/Resume)	□ Water Shut-Off	
_	Alter Casing	Fracture Treat	Reclamati	on	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	⊠ Temporari			
	Convert to Injection	☐ Plug Back	□ Water Dis	posal		
Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for Devon Energy Production Co as follows: MURU pump track pressure recorder. BDMO pull	ork will be performed or provided operations. If the operations rebandonment Notices shall be fifinal inspection), LP respectfully requests c. Pressure up the casing mp fruck.	give subsurface locations and measure the Bond No on file with BLM/BIA sults in a multiple completion or reconled only after all requirements, including approval to run a MIT on the reto 500 psi for 30 minutes, using a top of CIBP — SEE Co	Required subsempletion in a new appletion in a new appletion, and reclamation, before the control of the contro	equent reports shall b w interval, a Form 31 have been completed ell	ne filed within 30 days 60-4 shall be filed once I, and the operator has	
TA'ing well to bring well into OCD compliance, until well can be evaluated.				Γ	RECEIVED	
14 mg wen to bring wen into OOD compliance, until wen can be evaluated.					ALIG 2 2 2012	
SEE ATTACHEI	A	cepted f	or record	NMOCD ARTES		
CONDITIONS O	1	NMO	T 1 _ 1=	NMOCD ATTES		
AST Reported 0:1			8	30/12		
	Electronic Submission # For DEVON ENERO	145119 verified by the BLM Well GY PRODUCTION CO LP, sent to	the Carlsbad	ľ		
	ed to AFMSS for processin	g by BEVERLY WEATHERFORD	on 08/09/2012 TORY ANAL	(12BMW0531SE)		
Nume (Trinew Types) WILLAND	A OTAWI OTB	THE REGULA	TONT ANAL	131		
Signature (Electronic S		Date 08/07/20				
	THIS SPACE FO	OR FEDERAL OR STATE O	FFICE USE	•		
Approved By J.D. W.A.	utlookg	Title LIE	7		Date 8/18/12	
onditions of approval, if any, are attached ertify that the applicant holds legal or equichly would entitle the applicant to condi-	uitable title to those rights in th	s not warrant or e subject lease Office	io .			



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

N. Pure Gold 8 Federal #2

- 1. Well may be approved to be TA/SI for a period of 90 days or until 11/20/2012 after successful MIT and subsequent report is submitted.
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or a NOI to P&A. Must be submitted by 10/20/2012.
- 4. Contact BLM 24 Hrs. prior to setting of CIBP and Cement so as it may be witnessed.