Office Office	State of Ne	w Mexico		Form C-103
<u>District 1</u> ~ (575) 393-6161	Energy, Minerals and	l Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> — (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-23292	
District III (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of I	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE []	FEE 🛛
<u>District IV</u> (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sama Pe, P	NIVI 67303	6. State Oil & Gas L	ease No.
87505				
SUNDRY NOTI	CES AND REPORTS ON W	VELLS	7. Lease Name or Ur	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS				
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS)	JATION FOR PERMIT" (FORM C	-101) FOR SUCH		39088
1. Type of Well: Oil Well	Gas Well Other SWD		8. Well Number 3	
2. Name of Operator		RECFIVE	9. OGRID Number	
COG Operating LLC	229137		229137	
3. Address of Operator	•	SEP 1 9 2012	10 Pool name or Wi	ildcat
One Concho Center, 600 W. Illinoi	s Avenue, Midland, TX 7970	1 รัพธ	Canyon (96184))
4. Well Location		NMOCD ARTES	Δ	
Unit Letter E :	2080 feet from the No			ne West line
Section 1	Township 198			County: Eddy
Section 1	11. Elevation (Show wheth			County, Ludy
	3464 Gr	ier DA, KKB, KT, GK, etc.,	,	
	1 2 10 1 01			
12 Charle	Ammonwista Day to India	nata Natana af Natica	Danam an Othan Da	.4.
12. Check A	Appropriate Box to Indic	cate Nature of Notice,	Report or Other Da	ita
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPO	ORT OF:
PERFORM REMEDIAL WORK ☐		REMEDIAL WOR		TERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	*****	AND A
TEIM ONAINET ADAINDON				AND A
DULL OF ALTER CASING				
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL [CASING/CEMEN	I JOB []	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MOLTIPLE COMPL [_ CASING/CEMEN	1 10B []	
	MOLTIPLE COMPL [1 JOB	П
DOWNHOLE COMMINGLE OTHER:	[OTHER:		including estimated date
OTHER: 13. Describe proposed or comp	leted operations. (Clearly sta	OTHER:	d give pertinent dates,	
OTHER: 13. Describe proposed or comp	leted operations. (Clearly start). SEE RULE 19.15.7.14	OTHER:	d give pertinent dates,	
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec	leted operations. (Clearly stork). SEE RULE 19.15.7.14 completion.	OTHER: ate all pertinent details, and NMAC. For Multiple Con	d give pertinent dates,	
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 7/20/12 Test BOP to 2750 lbs hold g	oleted operations. (Clearly strork). SEE RULE 19.15.7.14 completion.	OTHER: ate all pertinent details, and NMAC. For Multiple Con	d give pertinent dates,	
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or rec 7/20/12 Test BOP to 2750 lbs hold grades and the starting and the	oleted operations. (Clearly strork). SEE RULE 19.15.7.14 completion.	OTHER: ate all pertinent details, and NMAC. For Multiple Con	d give pertinent dates,	
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion or recompletion of the starting and proposed we proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion of the starting proposed completion or recompletion of the starting proposed completion or recompletion of the starting proposed completion of the starting proposed completion of the starting proposed completion or recompletion of the starting proposed completion or recompletion of the starting proposed completion or recompletion or recom	pleted operations. (Clearly states ork). SEE RULE 19.15.7.14 completion.	OTHER: ate all pertinent details, and NMAC. For Multiple Con circ clean	d give pertinent dates, mpletions: Attach well	
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion or recompletion of the starting and proposed we proposed completion or recompletion or recompletion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion or recomplet	pleted operations. (Clearly states ork). SEE RULE 19.15.7.14 completion. good, Drill cmt from 40'-145	OTHER: ate all pertinent details, and NMAC. For Multiple Conditions of the conditio	d give pertinent dates, mpletions: Attach well	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly states ork). SEE RULE 19.15.7.14 completion. good, Drill cmt from 40'-145 cmt 6507'-7008' pressure csg	OTHER: ate all pertinent details, and NMAC. For Multiple Conditions of the conditio	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion or recompletion of recompletion of recompletion or recom	pleted operations. (Clearly states of the control of the completion. good, Drill cmt from 40'-145 cmt 6507'-7008' pressure csg RATED FROM 7712 TO 7718 , 40 SHOTS, 8020 TO 8035, 3	OTHER: ate all pertinent details, and NMAC. For Multiple Conditions of the conditio	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion of recompletion or recompletion of recompletion of recompletion of recompletion of recompletion of recompletion or recompletion of recompletion or recom	pleted operations. (Clearly states of the completion.) good, Drill cmt from 40'-145 cmt 6507'-7008' pressure csg RATED FROM 7712 TO 7718 40 SHOTS, 8020 TO 8035, 31 JEW PBTD@ 8175'	OTHER: ate all pertinent details, and NMAC. For Multiple Conditions of the conditio	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recom	pleted operations. (Clearly states of the control of the completion. good, Drill cmt from 40'-145 cmt 6507'-7008' pressure csg RATED FROM 7712 TO 7718 , 40 SHOTS, 8020 TO 8035, 31EW PBTD@ 8175' fs w/14,000 gal 15%	OTHER: ate all pertinent details, and NMAC. For Multiple Condition of the	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recom	pleted operations. (Clearly state of the control of the completion. good, Drill cmt from 40'-145 cmt 6507'-7008' pressure csg RATED FROM 7712 TO 7718 , 40 SHOTS, 8020 TO 8035, 31 IEW PBTD@ 8175' fs w/14,000 gal 15% holes, 7912'- 7930', 30 shots	OTHER: ate all pertinent details, and NMAC. For Multiple Condition of the	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition of the	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO	bore diagram of
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition of the	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFAC	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Conditions of the condition of th	d give pertinent dates, mpletions: Attach well t good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFAC	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 15 15 15 15 15 15 15 15 15 15 15 15 15 1	d give pertinent dates, impletions: Attach well t good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFAC	lbore diagram of 7770, 20 SHOTS, 7800 DE, DUMP 25' OF hots fired.
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 615 63'-6908, 30 SHOTS, 6857' 0 gals %15 38' 16 shots 6710-6724' 1	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACTOR GUNS	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 615 63'-6908, 30 SHOTS, 6857' 0 gals %15 38' 16 shots 6710-6724' 1	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACTOR GUNS	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 615 03'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACT-6868' 22 SHOTS, all states and the states and the states are states as a state of the states are states as a state	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 615 03'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACT-6868' 22 SHOTS, all states and the states and the states are states as a state of the states are states as a state	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 615 03'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACT-6868' 22 SHOTS, all states and the states and the states are states as a state of the states are states as a state	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98
OTHER: 13. Describe proposed or compostarting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompletion	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 15 15 18 16 shots 6710-6724 1 TAG RBP@ 6824 CIRC of the best of my knowledge	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE-6868' 22 SHOTS, all states and belief.	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98 Out, UNSET RBP TOOH
OTHER: 13. Describe proposed or comp of starting any proposed we proposed completion or recompletion of recompletion or recompletion of recom	pleted operations. (Clearly state of the content of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 615 03'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE-6868' 22 SHOTS, all states and belief.	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98 Out, UNSET RBP TOOH
OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recompletion of the starting and the starting and proposed completion or recompletion of recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion or reco	pleted operations. (Clearly state of the control of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% %15 13'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1 ., TAG RBP@ 6824' CIRC to the best of my knowledg Regulatory Analyst	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE-6868' 22 SHOTS, all selection of the selection	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98 Dut, UNSET RBP TOOF
OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recompletion of recompletion	pleted operations. (Clearly state of the control of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% 15 15 18 16 shots 6710-6724 1 TAG RBP@ 6824 CIRC of the best of my knowledge	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE-6868' 22 SHOTS, all selection of the selection	lbore diagram of 7770, 20 SHOTS, 7800 CE, DUMP 25' OF hots fired. 2' 44 shots total of 98 Out, UNSET RBP TOOH
OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recompletion of the starting and the starting and proposed completion or recompletion of recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion of the starting and proposed completion or recompletion or reco	pleted operations. (Clearly state of the control of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% %15 13'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1 ., TAG RBP@ 6824' CIRC to the best of my knowledg Regulatory Analyst	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE SHOTS, all selection of the surface of the sur	// Ibore diagram of // // // // // // // // // // // // //
OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recompletion of recompletion	pleted operations. (Clearly state of the control of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% %15 13'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1 ., TAG RBP@ 6824' CIRC to the best of my knowledg Regulatory Analyst	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE SHOTS, all selection of the surface of the sur	// Ibore diagram of // // // // // // // // // // // // //
OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recompletion of recompletion	pleted operations. (Clearly state of the control of	OTHER: ate all pertinent details, and NMAC. For Multiple Condition circ clean to 500 psi for 30 min, test, 12 SHOTS, 7738 TO 774 30SHOTS, ALL FIRE CHE 00 gal 15% %15 13'-6908, 30 SHOTS, 6857' 0 gals %15 3' 8' 16 shots 6710-6724' 1 ., TAG RBP@ 6824' CIRC to the best of my knowledg Regulatory Analyst	d give pertinent dates, impletions: Attach well to good 2, 8 SHOTS, 7760 TO CK GUNS ON SURFACE-6868' 22 SHOTS, all selection of the selection	1bore diagram of 7770, 20 SHOTS, 7800 DE, DUMP 25' OF hots fired. 2' 44 shots total of 98 Dut, UNSET RBP TOOH9/17/12 NE: _432-221-0467