

Substitit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-20541
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8838
7. Lease Name or Unit Agreement Name ETZ State Unit
8. Well Number 105
9. OGRID Number 013837
10. Pool name or Wildcat Grbg Jackson SR Q Grbg SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Injection

2. Name of Operator
Mack Energy Corporation

3. Address of Operator
P. O. Box 960 Artesia, NM 88211-0960

4. Well Location
Unit Letter G 1980 feet from the North line and 1980 feet from the East line
Section 16 Township 17S Range 30E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3679' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP at 2044' w/ 35' cement cap.
3. Circ hole with mud gel. 1092'
4. Perf at 1042' squeeze plug 50' below and above base of salt. - TA9
5. Perf at 582' squeeze plug 50' above and below 8 5/8" shoe. - TA9
6. Set 10 sx surface plug. - PLACE cnt. inside? outside of CS9 0'-60' - TA9
7. Install dry hole marker.

Notify OCD 24 HRS Prior to ANY work DONE

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 6/15/2005
Type or print name Jerry W. Sherrell E-mail address jerry@mackenergycorp.com Telephone No. (505)748-1288
For State Use Only
APPROVED BY: [Signature] TITLE _____ DATE JUN 27 2005
Conditions of Approval (if any): _____

MACK ENERGY CORPORATION
 ETZ STATE 105
 SEC 16 T17S R30E 1980FNL 1980FEL

- 1 Notify OCD 24hrs of plugging
- 2 Set CIBP 2044' w/35'cmt cap circ mud
- 3 Perf 1042' btm salt squeeze 100sks plug
- 4 Perf 582' Squeeze cmt 50' above and below surfe
- 5 Set 10sk surface plug
- 6 Install dry hole marker

