Submit 3 Copies 10 Appropriate District	State of N	lew Mexico			rorm (J-103
Office District I	Energy, Minerals at	nd Natural Resou	arces		March 4	1, 2004
1625 N. French Dr., Hobbs, NM 88240 District II			30	ELL API NO. 0-015-34137		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				Indicate Type	of Lease	
District III 1220 South St. Francis Dr.			15.	STATE		l
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6.	State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTIC	ES AND REPORTS ON	WELLS			or Unit Agreement N	ame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				ornillo State		
1. Type of Well:			L	Well Number		j
Oil Well Gas Well	Other	BECEL	VED #1			
2. Name of Operator		RECEI	9.	OGRID Num	ber	
Nadel and Gussman Permian, LLC		JUN 3 0		55615		-
3. Address of Operator			1/). Pool name o	r Wildcat	
601 N. Marienfeld Suite 508 Midlan	d, Texas 79701	OCO-AM	C	emetery Morro	W	
4. Well Location				······································		
	nship 21-S Range 11. Elevation (Show whe	24-E	NMPM	n the West		
	3,798'				p. T. C. Salar	
Pit or Below-grade Tank Application (For						
Pit Lecation: Let 4 Sect 18 Twp 21	-SRng 24-EPit type Res	erve _Depth to Groun	dwater +160'	_Distance from n	earest fresh water well 1	900,+_
Distance from nearest surface water 1000	'+ Below-grade Tank Lo	cation ULSe	ectTwp	Rng	;	
feet from theline and	feet from the	line				l
L						
	• • • • • •				_	
	ppropriate Box to Ind	icate Nature of				
NOTICE OF INT	TENTION TO:		SUBSE	QUENT RE	PORT OF:	
	TENTION TO:			QUENT RE		G □
NOTICE OF INT	TENTION TO:	REMED COMME	SUBSE PIAL WORK	QUENT RE	PORT OF:	G []
NOTICE OF INT	PLUG AND ABANDON	REMED COMME	SUBSE PIAL WORK ENCE DRILLII E TEST AND	QUENT RE	PORT OF: ALTERING CASIN PLUG AND	
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	REMED COMME CASING CEMEN OTHER	SUBSE PIAL WORK ENCE DRILLII FOR TEST AND IT JOB : Amended R	QUENT RE	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT	
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly sk). SEE RULE 1103. For fiety meeting and rig up casing cond @ 10.5 ppg lite-crete plus add st and 1,500 psi. N/U BOP, cho	REMED COMME CASING CEMEN OTHER state all pertinent of Multiple Completer Multiple Completer and 48 bbl tail @ 14	SUBSE PLAN WORK ENCE DRILLII FOR TEST AND TOB Amended R details, and giretions: Attach	eport we pertinent dan wellbore diag K-55 LTC set @ 1 ment. Displaced w	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Tes, including estimater am of proposed contact and proposed contact and proposed p	ted date
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed worth or recompletion. 66/23/05 R/U & L/D 8" drill collars. Hold satisficulate w/ rig pumps. Cement w/ 103 bbls lest circulate d 145sx. WOC 18 Hrs. 66/24/05 WOC cut off and install wellhead to Drill out float collar and test casing to 1,500 psi	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly sk). SEE RULE 1103. For fety meeting and rig up casing cond @ 10.5 ppg lite-crete plus add st and 1,500 psi. N/U BOP, cho i for 30 min OK.	REMED COMME CASING CEMEN OTHER state all pertinent of Multiple Completer Multiple Complet	SUBSE PLAN WORK ENCE DRILLII ETEST AND TOB : Amended Reletails, and give etions: Attach 2.5/8" casing 40# .8 ppg class C ce low 5,000 psi high	eport eport ve pertinent dan wellbore diag K-55 LTC set @ 1 ment. Displaced w	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Tes, including estimater am of proposed contact and proposed contact and the second seco	ted date appletion and alug ing head.
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 66/23/05 R/U & L/D 8" drill collars. Hold sa circulate w/ rig pumps. Cement w/ 103 bbls lest circulated 145sx. WOC 18 Hrs. 66/24/05 WOC cut off and install wellhead to Drill out float collar and test casing to 1,500 ps.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly sk). SEE RULE 1103. For fety meeting and rig up casing cond @ 10.5 ppg lite-crete plus add st and 1,500 psi. N/U BOP, cho i for 30 min OK.	REMED COMME CASING CEMEN OTHER state all pertinent of Multiple Completer Multiple Complet	SUBSE PLAN WORK ENCE DRILLII ETEST AND TOB : Amended Reletails, and give etions: Attach 2.5/8" casing 40# .8 ppg class C ce low 5,000 psi high	eport eport ve pertinent dan wellbore diag K-55 LTC set @ 1 ment. Displaced w	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Tes, including estimater am of proposed contact and proposed contact and the second seco	ted date appletion and alug ing head.
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed worth or recompletion. 66/23/05 R/U & L/D 8" drill collars. Hold satisficulate w/ rig pumps. Cement w/ 103 bbls lest circulate d 145sx. WOC 18 Hrs. 66/24/05 WOC cut off and install wellhead to Drill out float collar and test casing to 1,500 psi	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. For fety meeting and rig up casing of and @ 10.5 ppg lite-crete plus add st and 1,500 psi. N/U BOP, cho is for 30 min OK. bove is true and complete losed according to NMOCD green	REMED COMME CASING CEMEN OTHER state all pertinent of Multiple Completer Multiple Complet	SUBSE PLAN WORK ENCE DRILLII ETEST AND T JOB : Amended R details, and give etions: Attach 25/8" casing 40# 1.8 ppg class C ce low 5,000 psi high knowledge and 1 permit or and	eport eport ve pertinent dan wellbore diag K-55 LTC set @ 1 ment. Displaced w	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Tes, including estimater am of proposed contact and proposed contact and the second seco	ted date appletion and alug ing head.
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 86/23/05 R/U & L/D 8" drill collars. Hold sa circulate w/ rig pumps. Cement w/ 103 bbls lest circulated 145sx. WOC 18 Hrs. 86/24/05 WOC cut off and install wellhead to Drill out float collar and test casing to 1,500 psi I hereby certify that the information all grade tank has been/will be constructed or circulated.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. For fety meeting and rig up casing of and @ 10.5 ppg lite-crete plus add st and 1,500 psi. N/U BOP, cho is for 30 min OK. bove is true and complete losed according to NMOCD green	REMED COMME CASING CEMEN OTHER State all pertinent of Multiple Complete The Multiple Com	SUBSE PIAL WORK ENCE DRILLII ETEST AND T JOB : Amended R details, and giretions: Attach 25/8" casing 40# 8 ppg class C ce low 5,000 psi high knowledge and permit or an	eport eport ve pertinent data wellbore diage K-55 LTC set @ 1 ment. Displaced well belief. I furth a (attached) altern DATE	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Les, including estimater arm of proposed contact and proposed contact and bumped places. BHA and TIH install rotations of correctify that any pit of particle of the correctify that any pit of the correctify that any pit of the correction of the co	ted date appletion and alug ing head.
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 66/23/05 R/U & L/D 8" drill collars. Hold sa circulate w/ rig pumps. Cement w/ 103 bbls lescirculated 145sx. WOC 18 Hrs. 66/24/05 WOC cut off and install wellhead te Drill out float collar and test casing to 1,500 psi I hereby certify that the information a grade tank has been/will beconstructed or circulated 145sx.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly sk). SEE RULE 1103. For and (a) 10.5 ppg lite-crete plus add (a) 10.5 ppg lite-crete plu	REMED COMME CASING CEMEN OTHER State all pertinent of Multiple Complete The Multiple Com	SUBSE PIAL WORK ENCE DRILLII ETEST AND T JOB : Amended R details, and giretions: Attach 25/8" casing 40# 8 ppg class C ce low 5,000 psi high knowledge and permit or an	eport eport ve pertinent dan wellbore diag K-55 LTC set @ 1 ment. Displaced w h OK. Strap new I	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Les, including estimater arm of proposed contact and proposed contact and bumped places. BHA and TIH install rotations of correctify that any pit of particle of the correctify that any pit of the correctify that any pit of the correction of the co	ted date appletion and alug ing head.
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 66/23/05 R/U & L/D 8" drill collars. Hold sa circulate w/ rig pumps. Cement w/ 103 bbls lescirculated 145sx. WOC 18 Hrs. 66/24/05 WOC cut off and install wellhead te Drill out float collar and test casing to 1,500 psi I hereby certify that the information a grade tank has been/will beconstructed or circulated 145sx.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly sk). SEE RULE 1103. For and (a) 10.5 ppg lite-crete plus add (a) 10.5 ppg lite-crete plu	REMED COMME CASING CEMEN OTHER State all pertinent of Multiple Complete The Multiple Com	SUBSE PIAL WORK ENCE DRILLII ETEST AND T JOB : Amended R details, and giretions: Attach 25/8" casing 40# 8 ppg class C ce low 5,000 psi high knowledge and permit or an	eport eport ve pertinent data wellbore diage K-55 LTC set @ 1 ment. Displaced well belief. I furth a (attached) altern DATE	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Les, including estimater arm of proposed contact and proposed contact and bumped places. BHA and TIH install rotations of correctify that any pit of particle of the correctify that any pit of the correctify that any pit of the correction of the co	ted date appletion and alug ing head.
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed worth or recompletion. 66/23/05 R/U & L/D 8" drill collars. Hold satisficulate w/rig pumps. Cement w/ 103 bbls lest circulated 145sx. WOC 18 Hrs. 66/24/05 WOC cut off and install wellhead to Drill out float collar and test casing to 1,500 psi I hereby certify that the information all grade tank has been/will be constructed or circulated 145sx. Type or print name Josh Fernau (This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly sk). SEE RULE 1103. For and @ 10.5 ppg lite-crete plus address and 1,500 psi. N/U BOP, chois for 30 min OK. bove is true and complete losed according to NMOCD grant address and address and address and address according to NMOCD grant address and address according to NMOCD grant according to NMO	REMED COMME CASING CEMEN OTHER State all pertinent of Multiple Complete The Multiple Com	SUBSE PIAL WORK ENCE DRILLII ETEST AND T JOB : Amended R details, and giretions: Attach 25/8" casing 40# 8 ppg class C ce low 5,000 psi high knowledge and permit or an	eport eport ve pertinent data wellbore diage K-55 LTC set @ 1 ment. Displaced well belief. I furth a (attached) altern DATE	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT Les, including estimater arm of proposed contact and proposed contact and bumped places. BHA and TIH install rotations of correctify that any pit of particle of the correctify that any pit of the correctify that any pit of the correction of the co	ted date appletion and alug ing head.