
Subtitit 3 Copies To Appropriate District	State of N	lew Mexico	Form C-103	
Office District I	Energy, Minerals and Natural Resources		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240 District 11			WELL API NO. 30-015-20550	
1301 W. Grand Ave., Artesia, NM 88210	-	ATION DIVISION	5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE 🛛 FEE	
District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-2130	
		EN OR PLUG BACK TO A	7. Lease Name or Unit Agree ETZ State Unit	ment Name
PROPOSALS.)			8. Well Number 103	
1. Type of Well: Oil Well	Gas Well Other Inje	RECEIVED		
	ergy Corporation	JUL 1 3 2005	9. OGRID Number 01383'	7
3. Address of Operator	060 A NIM 99311	POBH-WHITEDIA	I 0. Pool name or Wildcat	
4. Well Location	x 960 Artesia, NM 88211-	0960	Grbg Jackson SR Q Grbg SA	
Unit LetterC	660feet from the	North line and	1980 feet from the V	Vest <sub>line</sub>
Section 16	Township		NMPM County	Eddy
Section		ther DR, RKB, RT, GR, etc	· · · · · · · · · · · · · · · · · · ·	
3685' GR				
Pit or Below-grade Tank Application or Closure				
Pit typeDepth Groundw	aterDistance from near	est fresh water wellD	istance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bb1s; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				
PULL OR ALTER CASING	MULTIPLE COMPL	L CASING/CEME	NT JOB	
OTHER:		OTHER:		П
	pleted operations. (Clearly s		nd give pertinent dates, including	estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Notify OCD 24 hours prior to starting plugging operations.				
2. Set CIBP at 2433' w/ 35' cement cap.				
3. Circ hole with mud gel.				
4. Perf at 1100' squeeze plug 50' below and above base of salt. WOC and tag.				
<ul><li>5. Perf at 601' squeeze plug 50' above and below 8 5/8" shoe. WOC and tag.</li><li>6. Perf at 60' squeeze cement to surface inside and outside of casing. WOC and tag.</li></ul>				
7. Install dry hole marker.				
7. Instant dry note marker.				
	•			
			•	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan				
SIGNATURE Jeny W.		ITLE Production Clerk	DATE_7/12	2/2005
Type or print name Jerry W. Sherr	ell E-n	nail address: jerrys@mack	Terephone ive	(505)748-1288
For State Use Only	<i>200</i>	Field Super		1 4 0000
APPROVED BY: Conditions of Approval (if any):	ТТ	ITLE	DAYE_	1 4 2005

## MACK ENERGY CORPORATION ETZ STATE 103 SEC 16 T17S R30E 660FNL 1980FWL



1.1400 Squagaria