Submit I Copy To Appropriate District Office	Office Energy, Minerals and Natural Resources		Form C-103 Revised August 1, 2011
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II - (575) 748-1283	OIL CONSERVATI	ON DIVISION	30-015-40371
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		o. State on & Gas Bease 116.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name LOS MEDANOS 36 23 30 STATE
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 1H
2 Name of Operator		9. OGRID Number	
Chevron U S A, Inc.		4323	
3. Address of Operator 15 Smith Midland.	Road TX 79705		10. Pool name or Wildcat WC-015 G-OG S233036D; BONE SPRING
4. Well Location		· ·	WC-013 G-OG 5253030D, BONE SERING
Unit Letter M: 200' feet from the South line and 660' feet from the West line			
Section 36	Township 23S	Range 30E	NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3422' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON			
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMENT	ΓJOB ⊠
DOWN TOLL COMMINICAL	1		
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
On 11/12/2012 drilled to a total depth of 13,740'. Ran 296 jts 2 (MARKER JTS AND DV TOOL AND PACKER) 5.5 csg, 17#, P-110 HC, LTC connection to 13740'. 65 spirolators to top of curve, then 28 bowsprings every 4th jt. Hold safety meeting, install cement head and lines. Test lines to 5000 psi. Pump first stage lead 800 sks 312 bbls 12.4 ppg, 35/65 Poz H + adds. First stage tail 1365 sks 313 bbls 14.5 ppg. Disp. w/318 bbls F/W. Bump plug. Lost returns 140 bbls into displacement. Increase pressure in incriments to 3900 psi and shear pins in openhole packer and inflate. Pressure bled to 3650 psi. Pressure back up to 4000 psi to confirm packer set. OK, bleed back 5 bbls and floats held. Drop DV bomb, wait 20 min and open DV tool. Circ B/U from DV tool. 5 bbls cmt to the pit.Begin pumping 2nd stage 20 bbls FW Lead 304 sks 102 bbls 12.4ppg. Tail 112 sks 24 bbls 14.8 ppg. Disp. w/92 bbls F/W. Bump plug w/1500 psi over. Floats held. Full returns thru out job. 3 bbls to pit. Clean mud tanks, release rig @ 0500 hrs on 11/16/12.			
Spud Date:	Rig Releas	e Date:	NMOCD ARTESIA
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby certify that the information above is true and complete to the best of my knowledge and benefit.			
SIGNATURE BY	TITLE D.	contatam. Consistint II	DATE 11/16/2012
SIGNATURE TITLE Regulatory Specialist II DATE 11/16/2012			
Type or print name Bryan Arrant (Agent for Chevron) E-mail address: bryan.arrant@chk.com PHONE: (405)935-3782			
For State Use Only			
APPROVED BY: 7/1000 Conditions of Approval (if any):	title <i>V.</i>	ist BSypewisn	DATE