			1				
Form 3160-5 (April 2004) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			ocd Artesia	5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an				· · · · · · · · · · · · · · · · · · ·	NMNM0417696 6. If Indian, Allottee or Tribe Name		
	rell. Use Form 3160-3 (A			0. H menan	, Mionee of The Mane		
<b>SUBMIT IN TRIPLICATE</b> - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Oil Well [	✓ Gas Well□□ Other			8. Well Na	me and No.		
2. Name of Operator OXY USA Inc. 16696				Lost Tank 3 Federal #26 9 API Well No.			
Ba. Address		<ol> <li>Phone No. (include area code)</li> <li>432-685-5717</li> </ol>		30-015-40769			
P.O. Box 50250       Midland, TX 79710       432-68         4. Location of Well (Footage, Sec., T, R., M., or Survey Description)			-5717		10. Field and Pool, or Exploratory Area Lost Tank Wolfcamp		
S - 845 FNL 887 FWL NWNW(\$) Sec 3 T22S R31E					11. County or Parish, State		
PBH - 680 FSL 1957 FEL SWSE(O) Sec 3 T22S R31E				Eddy	Eddy NM		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE,	REPORT, OF	R OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION							
Acidize       Deepen       Production (i)         Notice of Intent       Alter Casing       Fracture Treat       Reclamation         Subsequent Report       Casing Repair       New Construction       Recomplete         Final Abandonment Notice       Convert to Injection       Plug and Abandon       Temporarily         13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and				Abandon ssal	Water Shut-Off Well Integrity Other Spud., See Curt., test	t cs SZZ	
	wolved operations. If the operation inal Abandonment Notices shall be y for final inspection.)		ments, including rec	lamation, have bee	en completed, and the operat	or has	
DEC 1 9 2012 VMOCD ARTESIA		thached lade 12/19/12 point for rocord NMOCD		D	ED FOR REC EC 1 6 2012 OF LAND MANAGEM SBAD FIELD OFFICE	] ] 1ENT	
<ol> <li>I hereby certify that the for Name (Printed/Typed)</li> <li>David Stewart</li> </ol>	egoing is true and correct	Title R	egulatory Adviso	)r			
1	1	· · ·		1			
Signature Var'	174	Date	11/30		, 		
	THIS SPACE FOR I	FEDERAL OR S	TATE OFFI				
certify that the applicant holds leg which would entitle the applicant		does not warrant or n the subject lease C	Yitle Office		Date		
Fitle 18 U.S.C. Section 1001 and Tit States any false, fictitious or fraudu	le 43 U.S.C. Section 1212, make it a ilent statements or representations	crime for any person kr as to any matter within it	owingly and willf s jurisdiction.	ully to make to an	y department or agency of	the Unite	
/7							

•

`

- **1** 

(Instructions on page 2)

30

• •

5

.

## Lost Tank 3 Federal #26

Spud 17-1/2" hole 11/23/12, drill to 750'. RIH & set 13-3/8" 48# H-40 STC csg @ 750', cmt w/ 420sx (129bbl) PPC 13.5ppg followed by 420sx (101bbl) 14.8ppg all w/ additives, circ 376sx (115bbl) cmt to surf. Bumped plug, pressured up to 480#, pressure dripped to 100#, pumped 1bbl did not regain pressure, decision was made to leave cement head on casing and WOC per BLM requirements. Pump 200sx (48bbl) PPC, 14.8ppg, brought cmt to surface, pumped 70sx (16.8bbl) into cellar, WOC. NU & Test BOP's @ 250# low 5000# high. 11/27/12, RIH & tag cmt @ 520', test csg in increments of 300#, 800#, 1210#.holding each stage for 5min, pressure was bleeding off avg of 45#/5min.

AFTER DRILLING OUT CMT FROM 520' TO TOP OF FLOAT COLLAR AT 707' PRESSURE TESTED 13-3/8" CSG, FIRST STAGE TO 600#, PRESSURE STARTED BLEEDING OFF IMMEDIATELY, HELD FOR 12min PRESSURE DROPPED TO 540# PRESSURED UP TO PLANNED @ 1,210 AS REQUIRED BY BLM, HELD FOR 1min THEN BEGAN BLEEDING OFF RAPIDLY TO 480#, SECOND ATTEMPT WAS MADE PUMPING AT 10 SPM (1BBL/MIN) PRESSURE WOULD NOT STAY ABOVE 750 PSI. DECISION WAS MADE PER BLM TO RUN A CCL AND A MULTI ARM CALIPER LOG.

WAITING ON LOGGING EQUIPMENT TO RUN CCL AND MULTIARM CALLIPER LOGS ON 13-3/8 CSG, CONTINUE WAITING ON WIRELINE EQUIPMENT. TRIP IN HOLE WITH OPEN END DRILL PIPE TO 692'. PUMPED 10 BBL H20, 200SKS PREMIUM PLUS AT 14.8 PPG WITH 1% CACL 0.3% HALAD-23 (48 BBLS), DISPLACMENT 1 BBL H20 + 4 BBL BRINE. TRIP OUT OF HOLE TO 300 FT, CIRCULATE BOTTOMS UP, CLEAN OUT PIPE WITH 110 SPM, 422 GPM, PERFORM CEMENT HESITATION SQUEEZE WITH RIG PUMPS ,1,000 PSI, -1,100,-1,200 PSI, .91 BBL CEMENT SQUEEZED.W.O.C HOLD PRESSURE 6 HRS FROM 22:00 TO 04:00 PRESSURE BLED OFF FROM 1200 PSI TO 580 PSI.

PRESSURE TEST CASING TO 1000 PSI, 85 PSI BLEED OFF IN 30 MIN.

PULL WARE BUSHING, INSTALL TEST PLUG, PRESSURE TEST BLIND RAMS TO TEST PLUG TO 1000 PSI, 82 PSI BLEED OFF IN 30 MIN.

PRESSURE TEST 2" KILL LINE FROM PUMPS TO INSIDE KILL LINE VALVE TO 1000 PSI, NO BLEED OFF 10 MIN.

PRESSURE TEST BLIND RAMS TO TEST PLUG TO 1000 PSI, NO BLEED OFF IN 30 MIN.

PRESSURE TEST IN BETWEEN LOWER PIPE RAMS AND TEST PLUG TO 5000 PSI, GOOD 10 MIN TEST.

PRESSURE TEST IN BETWEEN UPPER PIPE RAMS AND TEST PLUG TO 5000 PSI, TEST FAILED, REPAIR CHECK VALVE AND PACKING GLAND.

RETEST IN BETWEEN UPPER PIPE RAMS AND TEST PLUG TO 5000, GOOD 10 MIN TEST. PULL TEST PLUG, INSTALL WARE BUSHING.

PRESSURE TEST CASING TO 1000 PSI, 50 PSI BLEED OFF IN 15 MIN.

TRIP IN HOLE WITH SLICK 12.25" BHA FROM SURFACE TO 395', TAG TOC, DRILL OUT HARD CEMENT FROM 395' TO 700', SWEEP AND CIRCULATE CASING CLEAN, PRESSURE TEST CASING AS FOLLOWS: EACH TEST BROUGHT UP TO 1,200 PSI AND HELD FOR 30 MIN. 1st TEST SHOWED 30%.PRESSURE LOSS F/ 1,198 PSI TO 827 PSI 2nd TEST SHOWED 23% PRESSURE LOSS F 1,185 psi to 906 psi

3rd TEST SHOWED 25% PRESSURE LOSS F 1,237 psi to 931 psi

TOH F/ 700' TO SURFACE W/ CLEAN OUT ASSEMBLY.

TRIP IN THE HOLE WITH DRILL PIPE PACKER. SET PACKER AT 571'. PRESSURED UP THE ANNULAR TO 1050 PSI. PRESSURE HELD. PRESSURED UP THROUGH THE DRILL PIPE TO 1080 PSI. PRESSURE DROPPED TO 785 PSI IN 10 MINUTES. IDENTIFIED POSSIBLE LEAK AT 594'.

PLAN FORWARD IS TO SET A RETREIVABLE BRIDGE PLUG AT 400' FOR TEMPORARY ABANDONMENT. A WELLHEAD CAP AND A PRESSURE GAUGE ON THE CASING VALVE WILL ALSO BE INSTALLED. RIG WILL BE LAID DOWN AND WILL MOVE TO THE NEXT LOCATION. A WORKOVER UNIT WILL BE MOVED TO THE LOST TANK 3 FED 26 TO PERFORM FURTHER REMEDIAL WORK.