Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API N		
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Ty		
1000 Rio Brazos Rd. Aztec. NM 87410		h St. Francis Dr. e, NM 87505	STATE	FEE X	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Sama P	e, INIVI 87303	6. State Oil &	c Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Nam Santa Fe Fee	ne or Unit Agreement Name	
PROPOSALS.) 1. Type of Well: Oil Well G	as Well X Other	RECEIVED	8. Well Num	ber ₀₀₁	
2. Name of Operator Chesapeake Operator		SÉP 1 4 2005	9. OGRID N	umber 147179	
3. Address of Operator P. O. Box 1	- · · ·	UUD-MATE OLA	. 1	e or Wildcat e;Abo South (Gas)	
4. Well Location			<u>-</u> -	· · · · · · · · · · · · · · · · · · ·	
Unit Letter I : 1980 feet from the South line and 660 feet from the East line					
Section 8	Township 9S	Range 25E hether DR, RKB, RT, GR,	NMPM etc.)	CountyChaves	
3651' GR Pit or Below-grade Tank Application or Closure					
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil	Below-Grade Tank: Vo		Construction Materi		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
TEMPORARILY ABANDON	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	N 🔲 REMEDIAL W	DRILLING OPNS.	☐ ALTERING CASING ☐☐ ☐ P AND A ☐	
OTHER:		OTHER Drill	out/push CIBP to o	ld PBTD X	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion. 8-27-05 MIRU WS. Kill well. POOH w/126 jts. 2 3/8" tbg. RIH w/tbg. to TOC @ 4,010', break circ w/foam, wash, drill cmt. to CIBP @ 4,019', drill on CIBP 3.5 hrs. Did not make any hole, kill tbg w/7 bbls 2% KCL, start OOH w/tbg, pump 10 bbls 2% KCl					
down csg, cont. OOH w/tbg. Ck bit, found all 3 cones on bit loose. 8-30-05 Push CIBP to bottom @ 4,166'. Circ. off bottom 1 hr. w/foam. POOH w/ tbg., LD. Prepare to run pump in hole. 8-31-05 PU 1" x 12' GA and 1 1/4" x 24' RHBC pump RIH. Place well back on production.					
				and the second s	
			7	10 20 22 22 22 22 22 22 22 22 22 22 22 22	
				& 11 % + 	
				Stockety,	
I hereby certify that the information of	have is true and comple	ete to the hest of my know	edge and heliaf 14	urther certify that any nit or below	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.					
SIGNATURE SOME	Amen	TITLE Regulatory Analys	<u>t</u>	DATE 09/07/2005	
Type or print name Brenda Coffman For State Use Only		E-mail address: bcoffmar	@chkenergy.com	Telephone No. (432)687-2992	
APPROVED BY: SOR PE	CORDS ONLY	TITLE		DATE 2 0 2005	