Submit 5 Copies 10 Appropriate District Office	State of No	ew Mexico		Form	
District I	Energy, Minerals an	d Natural Resources		May 2	27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	015 20021	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-28931 5. Indicate Type of Lease		
District III	1220 South St. Francis Dr.		STATE STEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, 1	NM 87505	6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		o. blate on & da	S Deube 110.	
	CES AND REPORTS ON	WELLS	7. Lease Name or	Unit Agreement N	Vame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101)		GR 30 STATE			
PROPOSALS.)	CATION FOR PERMIT" (FORM C	-101) MECENTED	8. Well Number		
	Gas Well  Other	SEP 1 5 2005		2	
2. Name of Operator		DDD 1 10 2005	9. OGRID Numb	er	
COG Operating LLC		888-WHITEOM		229137	
3. Address of Operator			10. Pool name or		
550 W. Texas Ave., Suite 1300	Midland, TX 79701		Nash D	raw; Delaware	
4. Well Location					
Unit Letter <u>F</u> :	1650 feet from the	North line and	2310feet from	n the <u>West</u>	_line
Section 30	Township 2:	Range 30E	NMPM	County	Eddy
	11. Elevation (Show whet		c.)	APP DE	
		3124 GR			
Pit or Below-grade Tank Application O	or Closure				
Pit typeDepth to Groundw	aterDistance from neare	st fresh water well D	istance from nearest surf	ace water	
Pit Liner Thickness: mil	Below-Grade Tank: Volum	nebbls;	Construction Material		
12 Chack	Appropriate Box to Indi	onte Nature of Nation	Papart or Other	Data	
12. CHECK P	Appropriate Box to mai	cate mature or motice	, Report of Officer	Data	
NOTICE OF IN	ITENTION TO:	l su	BSEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK		REMEDIAL WO	·	ALTERING CASI	NC [
	1 200 7 (10) (110 011				NG []
TEMPORARILY ABANDON			RILLING OPNS.	P AND A	
	CHANGE PLANS	COMMENCE D CASING/CEME	<del></del>	P AND A	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	CASING/CEME	NT JOB		
TEMPORARILY ABANDON DULL OR ALTER CASING DUTHER:	CHANGE PLANS MULTIPLE COMPL	CASING/CEME OTHER:	NT JOB  Add Delaware perfs	& treat	
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or comp	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly s	CASING/CEME OTHER: tate all pertinent details, a	Add Delaware perfs	& treat es, including estim	□ ⊠ ated date
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compost of starting any proposed we	CHANGE PLANS MULTIPLE COMPL	CASING/CEME OTHER: tate all pertinent details, a	Add Delaware perfs	& treat es, including estim	□ ⊠ ated date
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or comp	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly s	CASING/CEME OTHER: tate all pertinent details, a	Add Delaware perfs	& treat es, including estim	□ ⊠ ated date
TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER:  13. Describe proposed or compost of starting any proposed we	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly s	CASING/CEME OTHER: tate all pertinent details, a	Add Delaware perfs	& treat es, including estim	□ ⊠ ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly s	CASING/CEME OTHER: tate all pertinent details, a	Add Delaware perfs	& treat es, including estim	□ ⊠ ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly sork). SEE RULE 1103. For  2 SPF @ 6976' 84' & 70	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or compof starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly sork). SEE RULE 1103. For  2 SPF @ 6976' 84' & 70	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29	CHANGE PLANS MULTIPLE COMPL  oleted operations. (Clearly sork). SEE RULE 1103. For  2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69)	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' - 84' & 70% acid. Swab well.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:	Add Delaware perfs and give pertinent date Attach wellbore diagr es). Acidize new pe	& treat es, including estim am of proposed co	ated date
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly sork). SEE RULE 1103. For 2 SPF @ 6976' – 84' & 70' acid. Swab well.  976' – 7092') w/ 40,000 gab well.	OTHER:  Cate all pertinent details, a Multiple Completions:  O72' – 92' (5142" hole of the second secon	Add Delaware perfs and give pertinent date. Attach wellbore diagrams. Acidize new performance with the performance of the performance with the performance w	& treat es, including estimates am of proposed contents (6976' – 7092) 30,000# 16/30	ated date mpletion
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly sork). SEE RULE 1103. For acid. See Section 2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.	CASING/CEME OTHER: tate all pertinent details, a Multiple Completions:  O72' – 92' (5142" hole  al Bfrac 25 gal w/ 90,00  to the best of my knowled	Add Delaware perfs and give pertinent date Attach wellbore diagrams. Acidize new performance of the performa	& treat es, including estimate am of proposed contents (6976' - 7092') 30,000# 16/30	ated date mpletion  2')
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly sork). SEE RULE 1103. For acid. See Section 2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.	CASING/CEME OTHER: tate all pertinent details, a Multiple Completions:  O72' – 92' (5142" hole  al Bfrac 25 gal w/ 90,00  to the best of my knowled	Add Delaware perfs and give pertinent date Attach wellbore diagrams. Acidize new performance of the performa	& treat es, including estimate am of proposed contents (6976' - 7092') 30,000# 16/30	ated date mpletion  2')
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  276' - 7092') w/ 40,000 gas well.  above is true and complete closed according to NMOCD gu	CASING/CEME OTHER: tate all pertinent details, a Multiple Completions:  OT2' - 92' (5142" hole  al Bfrac 25 gal w/ 90,00  to the best of my knowled  idelines , a general permit	Add Delaware perfs and give pertinent date. Attach wellbore diagrams. Acidize new performance of the perform	& treat es, including estimation of proposed contents (6976' – 7092) 30,000# 16/30  er certify that any pit sative OCD-approved	ated date mpletion  2')
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  pleted operations. (Clearly sork). SEE RULE 1103. For acid. See Section 2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.  2 SPF @ 6976' - 84' & 70' acid. Swab well.	OTHER:  Tate all pertinent details, a Multiple Completions:  O72' - 92' (5142" hole all Bfrac 25 gal w/ 90,00 details and the best of my knowled delines , a general permit )	Add Delaware perfs and give pertinent date. Attach wellbore diagrams. Acidize new performance of the perform	& treat es, including estimate am of proposed contents (6976' - 7092') 30,000# 16/30	ated date mpletion  2')
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (68 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For a control of	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:  OT2' - 92' (5142" hole all Bfrac 25 gal w/ 90,00 to the best of my knowled idelines , a general permit )  TLE Regulatory Analysis	Add Delaware perfs and give pertinent date. Attach wellbore diagraph. Acidize new performance of the perform	& treat es, including estimation of proposed constant of proposed constant of proposed constant of the constan	ated date mpletion  2')  or belowplan
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For a control of	CASING/CEME OTHER: tate all pertinent details, a Multiple Completions:  OT2' - 92' (5142" hole  al Bfrac 25 gal w/ 90,00  to the best of my knowled  idelines , a general permit	Add Delaware perfs and give pertinent date. Attach wellbore diagraph. Acidize new performance of the perform	& treat es, including estimation of proposed contents (6976' – 7092) 30,000# 16/30  er certify that any pit sative OCD-approved	ated date mpletion  2')  or belowplan
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For a cid. See RULE 1103. For a cid. Swab well.  2 SPF @ 6976' - 84' & 70' a cid. Swab well.  276' - 7092') w/ 40,000 gas ab well.  above is true and complete closed according to NMOCD guilled a complete closed according to E-mail address.	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:  O72' - 92' (5142" hole all Bfrac 25 gal w/ 90,00 details and the best of my knowled idelines , a general permit )  TLE Regulatory Analogues: pedwards@conche	Add Delaware perfs and give pertinent date. Attach wellbore diagraph. Acidize new performance of the perform	& treat es, including estimam of proposed constant of proposed constant of proposed constant of the constant o	ated date mpletion  2')  or below-plan 05  85-4340
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or comp of starting any proposed we or recompletion.  9-1-05 TOH w/ tbg. WO perf.  9-8-05 Perf Lower Delaware w/ 2 w/ 1500 gal 90/10 7-1/29  9-10-05 Frac Delaware perfs (69 resin coated sand. Swa	CHANGE PLANS MULTIPLE COMPL  Deleted operations. (Clearly sork). SEE RULE 1103. For a control of	CASING/CEME  OTHER: tate all pertinent details, a Multiple Completions:  O72' - 92' (5142" hole all Bfrac 25 gal w/ 90,00 details and the best of my knowled idelines , a general permit )  TLE Regulatory Analogues: pedwards@conche	Add Delaware perfs and give pertinent date. Attach wellbore diagraph. Acidize new performance of the perform	& treat es, including estimation of proposed constant of proposed constant of proposed constant of the constan	ated date mpletion  2')  or below-plan 05  85-4340