Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 HOBBS District II	October 13, 2009
District II	WELL API NO. 30-015-28278
1301 W Grand Ave Artesia NM 88210 OIL CONSERVATION DIVISIO	N 5. Indicate Type of Lease
District III MAR 11 2013 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	A EAST SHUGART UNIT
PROPOSALS.)	8. Well Number 78
 Type of Well: Oil Well ☐ Gas Well ☐ Other Name of Operator AMERICO ENERGY RESOURCES, LLC 	
2. Name of Operator AMERICO ENERGY RESOURCES, LLC	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
7575 SAN FELIPE STE. Houston, TX77063	
4. Well Location	· .
Unit Letter K : 2300' feet from the South line and 2300 feet from the East line	
Section 35 Township 18-S Range 31-I	
11. Elevation (Show whether DR, RKB, RT, C	GR, etc.)
12 Cheek Appropriets Doy to Indicate Nature of N	(eties Penert or Other Dete
12. Check Appropriate Box to Indicate Nature of N	ouce, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	_
1	CE DRILLING OPNS. P AND A
PULL OR ALTER CASING	CEMENT JOB
DOWNTIOLE COMMINITORE	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
proposed completion or recompletion. 1) MIRUWOR,N/U BOP RIH W/ FISH TOOLS & 2 7/8" TBING ATTEMPT TO FISH RODS & TBING, IF RODS AND TBING IS	
REMOVED -,RIH W/ 5 1/1" RBP & PKR, 2 7/8" TBING,SET RBP @ 3400'(60'ABOVE PERF'S @ 3460') PULL UP SET PKR,TEST RBP 600	
PSI,IF HOLDING,TEST BACKSIDE TO 600 PSI-IF LEAKING,SPOT 2SKS SAND ON RBP, START MOVE PKR UP HOLE TO ISOLATE HOLE IN CSG (SHOULD BE 15' BELOW WELLHEADS)	
2) ONCE HOLE IS ISOLATED CALL IN TO OFFICE W/ RESULTS	
3) IF HOLE IS 1000' OR BELOW N/D BOP,N/U FLANGE BACK CIRC UP 8 5/8" SET INJECTION RATE, PUMP CMT DOWN 5 ½" AND UP 8 5/8" CSG WHEN GOOD CMT IS SEEN IN PIT START FLUSH SPOT TOP OF CMT 100' ABOVE HOLE IN 5 ½" SHUT VAVLE ON 8	
5/8" AND PRESSURE 5 1/" TO 800 PSI S/I 5 1/" CSG WOC	
4) CHECK PRESSURE ON 5 ½" AND 8 5/8" CSG,RIH W/ 4 ½" BIT,BIT SUB,COLLARS TAG AND DRILL OUT CMT,TEST SQUEEZE TO 600 PS1,IF HOLDING	
5) IF HOLE IS AT SURFACE DIG UP WELLHEADS TO GOOD CSG, CUT OFF CSG'S, INSTALL NEW CSG'S AND INSTALL NEW	
WELLHEADS. 6) RIH & TAG SAND ON RBP @ 3400' CIRC BOTTOMS UP TO CIRC SAND OFF(DO NOT ROTATE BIT) CIRC CLEAN.	
7) POH W/2 7/8" TBING,L/D D.C.'S,BIT SUB,BIT,RIH W/ON/OFF TOOL,2 7/8" TBING TAG RBP CIRC REST OF SAND OFF	
RBP,LATCH ONTO & UNSET RBP,TOH L/D RBP. 8) RETURN WELL TO PRODUCTION	DEOENTED
9) Well returned to Production 7/4/2012	RECEIVED
()	MAR 1 2 2013
Spud Date: Rig Release Date:	VIAIN - 2 COIS
	NMOCD ARTESIA
I hereby certify that the information above is true and complete to the best of my kn	owledge and belief.
SIGNATURE	DATE 3/5/2013
	@americoenergy.com PHONE: 713-984-9700_
For State Use Only	, ,
APPROVED BY: ON DOOL TITLE DIST ESCAPE	U/S/\ DATE 3/14/13
Conditions of Approval (if any):	