Form 3160 5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

OCD	Artesia
-----	---------

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT				s: July 31, 2010		
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			5. Lease Serial No. NMNM83037			
			6. If Indian, Allotte			
SUBMIT IN TR	IPLICATE - Other instructions	on reverse side.	7. If Unit or CA/Ag	reement, Name and/or No.		
1. Type of Well				8. Well Name and No. JONES CANYON 4 FEDERAL 7		
2. Name of Operator Contact: JENNIFER A DUARTE			9. API Well No.			
Name of Operator     OXY USA WTP LP	E-Mail: jennifer_duarte@oxy.com			30-015-32293		
3a. Address PO BOX 4294 HOUSTON, TX 77210	3b. Phone No. (include area code) Ph: 713-513-6640		INDIAN BASII	10. Field and Pool, or Exploratory INDIAN BASIN; YESO		
4. Location of Well (Footage, Sec., 7	ocation of Well (Footage, Sec., T., R., M., or Survey Description)		II. County or Parish, and State			
Sec 4 T22S R24E SENE 1750FNL 990FEL		APR 19	2013 EDDY COUNTY, NM			
12. CHECK APP	ROPRIATE BOX(ES) TO IND	ICA LEMAGGE AF	UFRIAREPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off		
■ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity		
Subsequent Report	Casing Repair	■ New Construction	☐ Recomplete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	□ Temporarily Abandon			
_	☐ Convert to Injection	Plug Back	☐ Water Disposal			
following completion of the involved testing has been completed. Final Al determined that the site is ready for formation. We propose to do some work over the Rig 2- Kill the well. ND well head. 3- RIH open ended tubing and 4- Fill casing and test to 500 p 5- Pull tubing to 3560'. 6- RU cement trucks. Spot cell	ly resquest permission to plugba o by the below procedure.  NU BOP	a multiple completion or reconfer all requirements, included ack and recomplete this will be acked for reconference of the second for reconference of the s	ompletion in a new interval, a Form 3 ing reclamation, have been completed well into the Yeso  SEE ATTACHE CONDITIONS (	160-4 shall be filed once I, and the operator has		
14. I hereby certify that the foregoing is  Name(Printed/Typed) JENNIFEF	Electronic Submission #202444	VTP LP, sent to the Carl cessing by KURT SIMMO	sbad			
Signature (Electronic S	Submission)	Date 03/25/2	O13 APPR	APPROVED		
	THIS SPACE FOR FE	DERAL OR STATE	OFFICE USE			
Approved By		Title	APR 1	7 2013		
Conditions of approval, if any, are attached tertify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the subject		BUREAU OF LA	MANAGEME <b>NT</b> FIFE D. OFFICE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*


Provide CIOZ to NMOCD


## Additional data for EC transaction #202444 that would not fit on the form

## 32. Additional remarks, continued

7- RIH tubing and tag top of cement at 3450'. Report this depth to NMOCD. POH tubing. 8- RU wireline unit. Perforate Yeso 3200?-3300? (60 degrees phase). RD wireline unit. 9- Frac Yeso formation with 1,200 Bbls of X-Link gel with 140,000 lbs of 16/30 white sand with 9- Frac Yeso formation with 1,200 Bbls of Expedite.
10- RIH bit and clean to 3450'. POH.
11- RIH tubing and TAC to 3200'
12- RIH rod pump
13- Rig Down. Put the well on production.

Also, please see the attached wellbore diagrams for your use and review.





## Jones Canyon 4 Federal 7 30-015-32293 OXY USA WTP LP April 17, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by July 17, 2013.

- 1. Operator shall place a balanced cement plug from 8007'-7827' to seal off the DV tool at 7957'. Tag required.
- 2. Operator shall place a balanced cement plug from 7477'-7303' to seal off the Wolfcamp formation.
- 3. Operator shall place a balanced cement plug from 3558'-3345' to seal off the Bone Spring formation and the DV tool. Tag required.
- 4. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

10. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 041713