1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District\_III

1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 District IV
1220 S. St. Francis Dr. Santa Fe. NM 87505

**State of New Mexico** 

Form C-101 Revised December 16, 2011

RECEIVED Minerals and Natural Resources

APR 1.6 2013

Oil Conservation Division

220 South St. Francis Dr.

NMOCD ARTESIA

Santa Fe, NM 87505

Permit

Phone: (505) 476-	-3460 Fax: (505	5) 476-3462	<b>.</b>					e e janearen e legelek ili eta		1 tpsp		
AP	». PLICA	TION F	OR PERM	ΙΤ ΤΟ Γ	RILL, RI	E-ENT	FER. DEEP	EN. PLUGB	ACK, O	R ADD A ZONE		
			Operator Name						<sup>2</sup> OGRID Ni			
Lynx Petroleum Consultants, Inc. P.O. Box 1708								13645				
	. ,		Hobbs, NM 88240			•		<sup>3</sup> API Number				
									30-015-32374			
* Property Code Property						Name <sup>6</sup> Well No				6 Well No		
	312173		. WALTERTH				ION FEE			002		
					<sup>7</sup> Surfac	ace Location						
UL - Lot	Section	Township	Range .	Lot Idr			N/S Line	Feet From	E/W Line	. County		
D	21	22S	27E		85	5	NORTH	660	WEST	EDDY		
8 Pool Information												
					<del></del>							
CARLSBA	D;STRA	WN,SOUT	TH(GAS)							74120		
9 137	k Type		10 Well Type	Ad	Iditional V		<u>nformation</u>	12 Lease Type	13	Ground Level Elevation		
	BACK		GAS ROTARY			FEE		3115' GL				
	14 Multiple			15 Proposed Depth 16 Form			ation 17 Contractor		18 Spud Date			
5 1 . 0			11395' PBTE	Distance from nearest fresh water					1 1/4/2002 to nearest surface water			
Depth to Gro	und water			je .	earest fresh water	r weii		Distance	to nearest sur	race water		
			1	<sup>9</sup> Propos	sed Casing	g and	Cement Pro	gram				
Туре	Hole	e Size	Casing Size	Casin	ng Weight/ft	Setting Depth Sacks of Cement Estimated T						
	17 1/2 13 3/8			48#			352'	475	sx	Circ Surface		
	L	2 1/4	9 5/8	<u> </u>	36#	1772' 700			Circ Surface			
	8 3/4 7		23#			9000'	1250		. Circ Surface			
	6 1/8 4 1/2		11.6#		-	12030 315		SX	8365' Temp Survey			
	l		Casi	ng/Cem	ent Progra	am: A	dditional C	omments				
	-		-									
				Propose	d Blowou	t Prev	ention Prog	ram				
The second secon							Test Pressure Manufacturer					
Type Working					ig Tressure.							
DOUBLE RAM HYDRAULIC 5000							7500	D		SCHAFFER		
I hereby certi of my knowle			given above is tru	e and compl	ete to the best		OII (	CONSERVA	LION DIA	VISION		
I further cer	tify that th	e drilling p	it will be constru				, OIL C	ONSERVA.	ION DI	VISION		
			permit, or an	(attached)	alternative	Appro	ved By:			<b>⊙</b> .		
OCD-appro	ved pian 🔀	•	a de la companya de				PON					
Signature:	De	libre !	NKel	<i></i>	A April 1986 and		MUX		<del></del>			
Printed name: DEBBIE MCKELVEY							Title: Drs #					
Title: AGENT						Appro	ved Date: 4/24	1/2013 E	xpiration Dat	te:		
E-mail Addre	ess: debn	nckelvey(	@earthlink.net									
Date: 4/15/13 Phone: 575-392-3575							Conditions of Approval Attached					

## Walterthon Fee No. 2 Strawn Recompletion Procedure

**API No.:** 30-015-32374

Location: 855' FNL & 660' FEL Section 21, T-22S, R-27E

Eddy County, New Mexico

Elevation: 3115' GL

**KB:** +17'

**TD:** 12,030'

**PBTD:** 11,415'

Casing & Cement:

13-3/8", 48#/ft., ST&C @ 352' cmt. w/475 sx. circulated

9-5/8", 36#/ft., J-55, ST&C @ 1772' cmt. w/700 sx. circulated

7", 23#/ft., P-110&N-80, LT&C @ 9000'cmt. in two stages w/1250 sx. circulated

both stages

4-1/2", 11.6#/ft., P-110, LT&C @ 12,030' cmt. w/315 sx. TOC @ 8,365' by

temp survey

**Tubing:** 

2-3/8", 4.7#/ft., L-80, EUE w/PLS??? packer @, +/-11,350' KB

**Perforations:** 

Morrow: 11670'-72', 11735'-42', 11751'-59', 11819'-22'

CIBP: 11,575' Perforations:

Morrow: 11,466'-476'

**Proposed Perfs:** 

Strawn: 10270'-75', 10349'-58', 10414'-17'

### **Procedure:**

- 1. MIRU pulling unit. Kill well as required with 2% KCL TFW. ND wellhead. NU BOP.
- 2. Release 4-1/2" packer. Tally tubing OOH.
- 3. PU 3-3/4" bit & 4-1/2" casing scraper. TIH to 11,450'. Circulate and load hole w/2% KCL TFW. TOOH.
- 4. RU E&P wireline. Run and set CIBP @ 11,430'. Spot 35' cement on top of CIBP to abandon Morrow zone.
- 5. Test casing to 1500 psig for 15 minutes.
- 6. TIH w/tubing OE to 10,370'. Spot 2 bbls. 15% HCL-NE-FE acid. TOOH.
- 7. NU full opening 4-1/2", 5000 psig WP valve on top of BOP. RU E&P wireline w/FULL LUBRICATOR. Perforate Strawn section w/4 JSPF per the above schedule (80 holes total).

## Walterthon Fee No. 2 Stawn Recompletion Procedure

8. Lubricate in and set 4-1/2" production packer at +/-10,200' set up as follows:

Pump out plug Profile Nipple 6' Tailpipe Packer Profile Nipple On/Off Tool

- 9. ND 4-1/2" valve and test 2-3/8" tubing in hole to 8500 psig.
- 10. Circulate hole w/clean, corrosion inhibited 2% KCL TFW.
- 11. ND BOP. Land tubing and NU tree. Test annulus to 1000 psig for 15 minutes.
- 12. RU kill truck on tubing. Pump out plug and displace spot acid.
- 13. Flow/Swab well in and return to production. NOTE: Depending on rates and pressures recommendation may be made to reacidize with larger acid volume and/or ballsealers.

## LYNX PETROLEUM CONSULTANTS, INC. WOLFCAMP RECOMPLETION H<sub>2</sub>S PRECAUTIONS Walterthon Fee No. 2

### I. HYDROGEN SULFIDE TRAINING

All personnel, whether regularly assigned, contracted, or employed on an unscheduled basis, will receive training from a qualified instructor in the following areas prior to commencing operations on this well:

- 1. The hazards and characteristics of hydrogen sulfide  $(H_2S)$ .
- 2. The proper use and maintenance of personal protective equipment and life support systems.
- 3. The proper use of H<sub>2</sub>S detectors, alarms, warning systems, briefing areas, evacuation procedures, and prevailing winds.
- 4. The proper techniques for first aid and rescue procedures.

In addition, supervisory personnel will be trained in the following areas:

- The effects of H<sub>2</sub>S on metal components. If high tensile tubulars are to be used, personnel will be trained in their special maintenance requirements.
- 2. Corrective action and shut-in procedures when drilling or reworking a well and blowout prevention and well control procedures.

## II. H<sub>2</sub>S SAFETY EQUIPMENT AND SYSTEMS

- 1. Well Control Equipment:
  - A. A 5000 psig WP Blowout preventer with blind rams and pipe rams to accommodate all pipe sizes with properly sized closing unit will be furnished.
- 2. H<sub>2</sub>S detection and monitoring equipment:
  - A. 2 portable H<sub>2</sub>S monitors positioned on location for best coverage and response. These units have warning lights and audible sirens when H<sub>2</sub>S levels of 20 ppm are reached.

# WOLFCAMP RECOMPLETION H<sub>2</sub>S PRECAUTIONS Walterthon Fee No. 1 Page 2

## 3. Visual warning systems:

A. A wind direction indicator will be in place on the pulling unit doghouse.

### 4. Mud program:

A. The working fluid for this recompletion will be 2% KCL treated fresh water.

### 5. Metallurgy:

- A. Tubing, wellhead, and blowout preventers shall be suitable for H<sub>2</sub>S service.
- B. All elastomers used for packing and seals shall be H<sub>2</sub>S trim.

### 6. Communication:

A. Communications in company vehicles are provided by cellular telephones.

Cell1: 575-390-9063

Cell2: 575-390-9065

B. Land line (telephone) communications at Hobbs office. Phone: 575-392-6950

C: Emergency Numbers

911


Carlsbad Sheriff's Dept.: 575-887-1888 Carlsbad Hospital: 575-887-4100 Carlsbad Fire Dept.: 575-885-3125 Maljamar Fire Dept.: 575-676-4100


Hobbs Hospital: 575-492-5000

New Mexico State Police: 575-392-5588

### 8. Well testing:

A. No drill stem tests are being contemplated during this operation.





RECEIVED

District II

State of New Mexico

2013 | Energy, Minerals & Natural Resources Department

MMOCD ARTESIAL CONSERVATION DIVISION

1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

☐ AMENDED REPORT

1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

WELL LOCATION AND ACREAGE DEDICATION PLAT

<sup>1</sup> API Number	<sup>2</sup> Pool Code	<sup>3</sup> Pool Name	
30-015-32374	74120	CARLSBAD;STRAWN,SOUTH (G	AS)
<sup>4</sup> Property Code		<sup>6</sup> Well Number	
312173	W	002	
OGRID No.		<sup>9</sup> Elevation	
13645	LYNX PETROL	3115' GL	

<sup>10</sup> Surface Location

UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
D	21	22S	27E		855	NORTH	660	WEST	<b>EDDY</b>
			" Bott	om Hole	Location If	Different From	Surface		
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
12 Dedicated Acres	i Joint of	r Infill 14 C	Consolidation Co	ode 15 Orde	er No.				
320						•			

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

	/ / /			
-660'-0				17 OPERATOR CERTIFICATION  I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working
				interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.  4/15/13
			***. 	Signature McKeluy Date
	·			DEBBIE MCKELVEY, AGENT Printed Name
			/	debmckelvey@earthlink.net E-mail Address
,		,	· · · · · · · · · · · · · · · · · · ·	*SURVEYOR CERTIFICATION  I hereby certify that the well location shown on this
		·		plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.
				7/2/2002  Date of Survey
				Signature and Seal of Professional Surveyor: RONALD J. EIDSON
			·	ON FILE 32-11-0494
				Certificate Number