	State of New Mexico		Form C-103		
Office Energy, Minerals and Natu	ıral Resources		March	4, 2004	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.			
District II OIL CONCEDIA TION DIVISION		30-015-28418			
1501 W. Gland Avc., Artesia, 1401 66216		5. Indicate Type of Lease			
District III 1220 South St. France 1000 Rio Brazos Rd., Aztec, NM 87410		* -	X FEE	1	
District IV Santa Fe, NM 8	7505	6. State Oil & G		*	
1220 S. St. Francis Dr., Santa Fe, NM	•	LG-6459			
87505					
SUNDRY NOTICES AND REPORTS ON WELLS			or Unit Agreement N	Vame	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR		Agave AAJ State	e		
PROPOSALS.)	OK SOCII	8. Well Number	•		
1	RECEIVED	3		-	
Oil Well Gas Well Other P&A	TECEIVED	3			
2. Name of Operator	JUL 3 0 2004	9. OGRID Num	ber		
Vates Petroleum Cornoration		025575		İ	
3. Address of Operator	SP-ARTESIA	10. Pool name o	or Wildcat		
105 South Fourth Street, Artesia, NM 88210		Siegrest Draw A			
		Diegrest Diaw A			
4. Well Location	1: 1 6		.1 ***	.	
Unit Letter E: 1980 feet from the North	line and	feet from	the West	line	
	245	3.7. (D) (			
	inge 24E	NMPM Ed	ldy County		
11. Elevation (Show whether DR					
3814					
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form	ı C-144 must be attached	D			
Pit Location: UL Sect Twp Rng Pit type D	epth to Groundwater_	Distance from 1	nearest fresh water well		
Distance from nearest surface water Below-grade Tank Location UL	Sect Two	Rng	:		
			,		
feet from theline andfeet from theline					
12 Charle Ammaniata Day to Indianta N	Tatura of Matica	Damant am Otha	- Data		
12. Check Appropriate Box to Indicate N					
NOTICE OF INTENTION TO:	SUB	SEQUENT RE	EPORT OF:		
		SEQUENT RE		NG 🗌	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBS REMEDIAL WORK	SEQUENT RE	EPORT OF: ALTERING CASIN	_	
NOTICE OF INTENTION TO:	SUB	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND	NG   X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRII	SEQUENT RE	EPORT OF: ALTERING CASIN	_	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE	SUBS REMEDIAL WORK COMMENCE DRII CASING TEST AN	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND	_	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRII	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND	_	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRII CASING TEST AN CEMENT JOB	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND	_	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PUGANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:	SUBSTREMEDIAL WORK COMMENCE DRIE CASING TEST AN CEMENT JOB OTHER:	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT	X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:	SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and	SEQUENT RE  LING OPNS.  ID  I give pertinent da	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT	X ated date	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip	SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and	SEQUENT RE  LING OPNS.  ID  I give pertinent da	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT	X ated date	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:	SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and	SEQUENT RE  LING OPNS.  ID  I give pertinent da	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT	X ated date	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip	SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and	SEQUENT RE  LING OPNS.  ID  I give pertinent da	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT	X ated date	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.	SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and	SEQUENT RE  LING OPNS.  ID  I give pertinent da	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT	X ated date	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER: MULTIPLE COMPLETION  7/21/04 - MIRU and begin P&A procedures.	SUB: REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Ites, including estimates, including estimates	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 – MIRU and begin P&A procedures. 7/22/04 – Set 7" CIBP at 3940' with 35' cement on top. Circulated hole	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	SEQUENT RE	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Ites, including estimates, including estimates	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 – MIRU and begin P&A procedures. 7/22/04 – Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AND CEMENT JOB OTHER: pertinent details, and only completions: Att	SEQUENT RE  (	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Attes, including estimates, including estimate	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures. 7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establish	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AND CEMENT JOB OTHER: pertinent details, and only completions: Att	SEQUENT RE  (	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Attes, including estimates, including estimate	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 – MIRU and begin P&A procedures. 7/22/04 – Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 – Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and oble Completions: Attack with mud laden flue "Neat cement, shed circulation. Circulation.	SEQUENT RE  (	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Attes, including estimates, including estimates, and proposed contacts.  Spotted 30 sx Classass "C" Neat cement	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures. 7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establish	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and oble Completions: Attack with mud laden flue "Neat cement, shed circulation. Circulation.	SEQUENT RE  (	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Attes, including estimates, including estimates, and proposed contacts.  Spotted 30 sx Classass "C" Neat cement	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 – MIRU and begin P&A procedures. 7/22/04 – Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 – Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and oble Completions: Attack with mud laden flue "Neat cement, shed circulation. Circulation.	SEQUENT RE  (	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  Attes, including estimates, including estimates, and proposed contacts.  Spotted 30 sx Classass "C" Neat cement	X ated date mpletion	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER: SEE RULE 1103. For Multiple of recompletion.  7/21/04 - MIRU and begin P&A procedures.  7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hole Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "Completion of the state	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only the Completions: Attack with mud laden flue "Neat cement, shed circulation. Circulation. Circulation. Circulation. Circulation.	SEQUENT RE  LING OPNS.  D  Igive pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED.	ated date impletion is ss "C"	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures. 7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface. 7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REI	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only the Completions: Attack with mud laden flue "Neat cement. Shed circulation.	SEQUENT RE  LING OPNS.  ID  I give pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED.  ABANDONED.	inted date impletion is ss "C" to below-	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION  OTHER: SEE RULE 1103. For Multiple of recompletion.  7/21/04 - MIRU and begin P&A procedures.  7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hole Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "Completion of the state	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only the Completions: Attack with mud laden flue "Neat cement. Shed circulation.	SEQUENT RE  LING OPNS.  ID  I give pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED.  ABANDONED.	inted date impletion is ss "C" to below-	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON   TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER: COMPLETION  OTHER: Completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures.  7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.  7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REJ	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only completions: Attack with mud laden flue in the completion of	LING OPNS.  LING OPNS.  D  I give pertinent da ach wellbore diag  id. PUH to 3182'  culated 150 sx Cla  LUGGED AND  e and belief. I furtior an (attached) alter	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED  ABANDONED  Contact C	x  ated date mpletion  ss "C"  t to  or below- plan	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON   TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER: COMPLETION  OTHER: Completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures.  7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.  7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REJ	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only the Completions: Attack with mud laden flue "Neat cement. Shed circulation.	LING OPNS.  LING OPNS.  D  I give pertinent da ach wellbore diag  id. PUH to 3182'  culated 150 sx Cla  LUGGED AND  e and belief. I furtior an (attached) alter	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED.  ABANDONED.	x  ated date mpletion  ss "C"  t to  or below- plan	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 – MIRU and begin P&A procedures. 7/22/04 – Set 7" CIBP at 3940' with 35' cement on top. Circulated hole. Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 – Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface. 7/27/04 – Cut off wellhead and installed dry hole marker. FINAL REIST I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines.  SIGNATURE: TITLE: Regulation and the surface of the s	SUBSTREMEDIAL WORK  COMMENCE DRIFT  CASING TEST AND CEMENT JOB OTHER:  pertinent details, and oble Completions: Attained the completions of the completion o	SEQUENT RE  LING OPNS.  D  I give pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND  and belief. I furth or an (attached) alter  upervisor  D	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED  ABANDONED  Contact Company of the control of the contr	ated date mpletion  ss "C"  t to  or below- plan	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON   TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER: COMPLETION  OTHER: Completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures.  7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.  7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REJ	SUBSTREMEDIAL WORK  COMMENCE DRIFT  CASING TEST AND CEMENT JOB OTHER:  pertinent details, and oble Completions: Attained the completions of the completion o	SEQUENT RE  LING OPNS.  D  I give pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND  and belief. I furth or an (attached) alter  upervisor  D	EPORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED  ABANDONED  Contact C	ated date mpletion  ss "C"  t to  or below- plan	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures. 7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.  7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REI  I hereby certify that the information above is true and complete to the b grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE:  Title: Regulation Regulation and the standard second secon	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only completions: Attack with mud laden flue and circulation. Circulat	SEQUENT RE  LING OPNS.  D  Igive pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND  and belief. I furth or an (attached) alter upervisor  D  com Teleph	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED  ABANDONED  Contact Company of the control of the contr	ated date mpletion  ss "C"  t to  or below- plan	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures. 7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C 7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface. 7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REI  I hereby certify that the information above is true and complete to the b grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE:  Type or print name Tina Huerta E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE:  Type or print name Tina Huerta E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines E-mail address true and complete to the begrade tank has been/will be constructed or close	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only completions: Attack with mud laden flue and circulation. Circulat	SEQUENT RE  LING OPNS.  D  I give pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND  and belief. I furth or an (attached) alter  upervisor  D	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT  The standard of proposed configuration of proposed	ated date mpletion  ss "C"  t to  or below- plan	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multip or recompletion.  7/21/04 - MIRU and begin P&A procedures. 7/22/04 - Set 7" CIBP at 3940' with 35' cement on top. Circulated hol Neat cement at 3182' to 3003'. PUH to 1449'. Spotted 40 sx Class "C7/23/04 - Tagged cement at 1257'. Perforated 4 holes at 415'. Establis surface.  7/27/04 - Cut off wellhead and installed dry hole marker. FINAL REI  I hereby certify that the information above is true and complete to the b grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE:  Title: Regulation Regulation and the standard second secon	SUBS REMEDIAL WORK COMMENCE DRIFT CASING TEST AND CEMENT JOB OTHER: pertinent details, and only completions: Attack with mud laden flue and circulation. Circulat	SEQUENT RE  LING OPNS.  D  Igive pertinent da ach wellbore diag  id. PUH to 3182  culated 150 sx Cla  LUGGED AND  and belief. I furth or an (attached) alter upervisor  D  com Teleph	PORT OF: ALTERING CASIN PLUG AND ABANDONMENT  ABANDONED  ABANDONED  Contact Company of the control of the contr	ated date mpletion  ss "C"  t to  or below- plan	