

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUN 06 2013

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1315847592

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	MONCRIEF STATE #001	Facility Type	TANK BATTERY
Surface Owner	STATE	Mineral Owner	
		Lease No. (API#)	30-015-25017

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	23	17S	28E					EDDY

Latitude 32.81742

Longitude 104.15406

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	7bbls
Source of Release	Murphy switch on water tank	Date and Hour of Occurrence	06-01-2013	Date and Hour of Discovery	06-01-2013 9:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The murphy switch malfunctioned and did not turn on the transfer pump. We have replaced the murphy switch to prevent recurrence.

Describe Area Affected and Cleanup Action Taken.\*

Initially 10bbls of produced water were released due to a murphy switch failure on the water tank. We were able to recover 7bbls of produced water with a vacuum truck. The spill was completely contained inside the facility walls. All free fluid has been recovered. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: 	
Title: Senior Environmental Coordinator		Approval Date: JUN 07 2013	Expiration Date:
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06-05-2013 Phone: 432-661-6601			

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:

July 7, 2013

2RP-1679