Form 3160-5 (November 1994)

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ARTESIA, NM \$5310 Lease Serial No.

SUNDRY	NOTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill of reented
abandoned well.	form for proposals to drill of regrees, Use Form 3160-3 (APD) for such proposals

SUNDRY	NOTICES AND REPORT	NECHY	PP-S	. 1		NIVI-19172
						Allottee or Tribe Name
abandoned well.	Use Form 3160-3 (AP	D) for suc	n propos			ed for recon-
				-	7. If Unit of	A/Agreement, Name and/or No.
SUBMIT IN TRIPL	ICATE – Other insti	ructions	on revers	e side		
1. Type of Well					,	
Oil Well X Gas Well Other				8. Well Nam	e and No.	
2. Name of Operator				SHIRLEY YA FEDERAL #1		
LRE OPERATING, LLC.					3	
3a. Address c/o Mike Pippin LLC		3b. Ph	one No. (inclu	de area code)		30-005-62051
3104 N. Sullivan, Farmington, NM 87401		505-32	05-327-4573		10. Field and Pool, or Exploratory Area	
					Pecos Slop	pe Abo (82730)
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						
660' FNL & 1980' FEL Unit E	3				AND	
Sec. 33, T4S, R24E			Chaves Co			ounty, New Mexico
		·				
12. CHECK APPROPRIATE BOX	X(ES) TO INDICATE NA	ATURE OF	NOTICE, R	EPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	1				
X Notice of Intent	☐ Acidize	☐ Dee	nen	☐ Production	(Start/Resume)	Water Shut-Off
A route of mean	Alter Casing		ture Treat	Reclamation		Well Integrity
Subsequent Report	Casing Repair	☐ New	Construction	Recomplete		M Other P&A
	Change Plans	X Plug	and Abandon			
Final Abandonment Notice	Convert to Injection	Plug	Back	Water Disp	osal	
LRE would like to P&A the Abo perfs 3585'-88' & to W/P&A mud (25 sx gel/10 1/2" @ 1500'. Perf 3 sq outside 4-1/2" csq & 8 sx W/tbg @ 975', pump cm csgs w/cmt. Install P&A restore location. Any flow	nis Abo well as follow op Abo @ 3512'. Se 00 bbls water). Plug holes @ 1550'. W/p k inside csg. TOH. V t down tbg & circ to s marker with cmt to c w back will be into a c	s: MIRU: #2 (1550 kr @ ~13 VOC. Ta surface (~ omply with	SU. TOH voltage of the control of th	w/all production 35' & top w/25 p of Glorieta sh rate into Si g #3 (975'-Si DH. Cut off cs	on equipment of the second of	nt. Plug#1, 3535'-3435', 23'). WOC. Circ hole base of cmt behind 4- ix 47 sx cmt & SQ 39 sx 3/4" csg shoe @ 925'.
14. I hereby certify that the foregoing	is true and correct	l m				
Name (Printed/Typed) Mike Pippin Petroleum Engineer (Agent)					· (Agent)	
Signature	, /)	Date		1 edoled	in Engineer	(Agent)
Mila	Heapen		•	Αι	ugust 1, 201	13
	THIS SP	ACE FOR I	EDERAL OF	STATE USE		
Approved by /S/ DAV	ID R. GLAS	SS	PETROLI	zum Enginei	Date Date	AUG 0 8 2013
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would critically the applicant to conduct which would continue the applicant to conduct the conduction.	utable title to those rights in the		Office	ROSWELL	FIELD OFF	ICE

Title 18 USA Section (DOL makes in a Language for any figures on knowingly and willfully to make to any department or agency of the United States any false, fictitious or transfer or tra



SA @ 538'

10-3/4", 40.5#, J-55, ST&C Csg @ 925'. Cmted-600 sx & circ 45 sx to surf.

Glorieta @ 1500'

Ran 1500' of 1" tbg & pumped 300 sx cmt from 1,500' to surface

TOC calc to 2670' @ 75% Eff.

Fullerton @ 2886'

2-3/8" Tubing

Abo @ 3512'

Wolfcamp @ 4243'

Penn @ 4766'

Packer @ 3,523'

Abo Perfs: 3,585-88' (16 - 0.42" DIA holes)

CIBP @ 4,520' w/ 50' cement on top to 4470' Wolfcamp Perfs: 4,569-74' & 4,605-06' (16 - 0.42" DIA holes)

Wolfcamp Perfs: 4,656-62' (6 - 0.42" DIA holes) .

PBTD @ 5,193'

4-1/2", 9.5#, J-55, Csg @ 5,234' Cmted w/660 sx cmt

TD @ 5,234'

Lime Rock Resources Shirley YA Federal 1 Sec 33B-4S-24E **Chaves County, NM** Updated: Aug 1, 2013 PMP

Ele@ation: 4,976.1' GL

Date Spud: 9/23/83

Date TD'd: 10/15/83

Date Completed: 1/19/84				
<u>Zone</u>	Frac			
Abo	38,500 gals 30Q CO2 foamed x- link gel w/ 120,000# 20/40 sand			
Wolfcamp (Upper)	2,000 gals 7-1/2% spearhead acid			
Wolfcamp (Lower)	500 gals 5% spearhead acid			

Note: First gas sales on 4/4/06



LIME ROCK RESOURCES

PLUG #3: 975'-Surface: W/tbg @ 975', pump ~75 sx cmt & circ to Surface

10-3/4", 40.5#, J-55, ST&C Csg @ 925'. Cmted 600 sx & circ 45 sx to surf.

Ran 1500' of 1" tbg & pumped 300 sx cmt from 1,500' to surface

PLUG #2: 1550'-1450': Perf 3 SQ holes @ 1550' & SQ w/47 sx cmt

TOC calc to 2670' @ 75% Eff.

Elevation: 4,976.1' GL

Date Spud: 9/23/83

Date TD'd: 10/15/83

Date Completed: 1/19/84

Zone Frac

Abo 38,500 gals 30Q CO2 foamed x-link gel w/ 120,000# 20/40 sand

Wolfcamp (Upper) 2,000 gals 7-1/2% spearhead acid

Wolfcamp (Lower) 500 gals 5% spearhead acid

Note: First gas sales on 4/4/06

@ 2886'

Fullerton

Abo @ 3512'

Wolfcamp @ 4243'

Penn @ 4766'

PLUG #1: 3535'-3435': Set 4-1/2" CIBP @ 3535' & top w/25 sx cmt.

Abo Perfs: 3,585-88' (16 - 0.42" DIA holes)

CIBP @ 4,520' w/ 50' cement on top to 4470'

Wolfcamp Perfs: 4,569-74' & 4,605-06' (16 - 0.42" DIA holes)

Wolfcamp Perfs: 4,656-62' (6 - 0.42" DIA holes)

PBTD @ 5,193'

4-1/2", 9.5#, J-55, Csg @ 5,234' Cmted w/660 sx cmt

TD @ 5,234'

Lime Rock Resources
Shirley YA Federal 1
Sec 33B-4S-24E
Chaves County, NM
Updated: Aug 1, 2013 PMP

PROPOSED P&A

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office (RFO), prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet, and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.