

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-20421

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Jones "D"

8. Well Number 5

9. OGRID Number

10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

K. C. Resources, Inc.

3. Address of Operator

P. O. Box 6749, Snowmass Village, CO 81615

4. Well Location

Unit Letter L : 2310 feet from the S line and 330 feet from the W line

Section S18 Township T18S Range 27E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

CLOSED-LOOP SYSTEM ☐

OTHER: Correction Action ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU work over rig.
2. POOH with rods and tubing.
3. RIH with bit and scrapper for 5 1/2" casing.
4. POOH with tubing and scrapper. PU packer and RIH with plastic coated tubing and injection packer to +/- 1729'.
5. Circulate hole with packer fluid and set packer.
6. MIT well. If well will not MIT notify New Mexico UIC Department and inform them of problem and action to be taken to rectify problem. If well does MIT got to step 7.
7. Call New Mexico UIC Department and schedule MIT.

Service Company: United Drilling
Contact: Phelps White
Cell number: 575-626-7660

RECEIVED

SEP 16 2013

NMOCD ARTESIA

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Chief Financial Officer DATE 9/11/13

Type or print name James Spillane E-mail address: jspillane@crystalriveroil.com PHONE: 760-753-3330

For State Use Only

APPROVED BY: [Signature] TITLE [Signature] DATE [Signature]

Conditions of Approval (if any):

Contact Daniel Sanchez (Santa Fe NMOCD) 505-476-3493