Form 3160-5 (August 2007)

OCD Artesia

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

	Expires: July
Lease Ser	ial No.

١٥.	Lease Serial No.	
l	NMNM05608	
ŀ		

SUNDRY	NMNM05608	NMNM05608 6. If Indian, Allottee or Tribe Name				
Do not use the abandoned we	6. If Indian, Allotted					
SUBMIT IN TRI	7. If Unit or CA/Ag 891008508A	7. If Unit or CA/Agreement, Name and/or No. 891008508A				
 Type of Well ☐ Oil Well ☐ Gas Well ☐ Other 	er			8. Well Name and No. N INDIAN BASIN 21		
2. Name of Operator		NIFER A DUARTE	9. API Well No.			
OXY USA WTP LIMITED PTN	IRSHIP E-Mail: jennifer_duarte@	©oxy.com Phone No. (include area code	30-015-28621	30-015-28621-00-S1		
3a. Address	35. Ph		10. Field and Pool, or Exploratory INDIAN BASIN			
MIDLAND, TX 79710-0250						
4. Location of Well (Footage, Sec., T Sec 11 T21S R23E SENW 22		11. County or Parish, and State EDDY COUNTY, NM				
12. CHECK APPR	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	· ·	ТҮРЕ О	F ACTION			
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off		
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomplete			
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	workover Operations		
13. Describe Proposed or Completed Ope	☐ Convert to Injection	Plug Back	☐ Water Disposal			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fi Request for additional 60 to co is still the same. Please see the	operations. If the operation results in andonment Notices shall be filed onling nal inspection.)	n a multiple completion or reco y after all requirements, includ	ompletion in a new interval, a Form 31 ling reclamation, have been completed	160-4 shall be filed once I, and the operator has		
WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. I	NU BOP.		TACHED	to be bloom		
Request for additional 60 to co is still the same. Please see the WORKOVER PROCEDURE 1- Move the Rig 2- Kill the well. ND well head. It Abandonment Cement Plugs 3- RIH tubing open ended and 4- Spot 45 Sx of class ?H? cer water and pull 120?. 5- WOC for 8 hours, then RIH	tag cement plug at 8846? nent of 15.6 ppg from 8846? t and tag the cement plug that o	o 8615?. Flush the tubin cover Atoka formation to	g with fresh ONDITIONS I	NMOCD OF 19 2013		
	true and correct. Electronic Submission #22335 For OXY USA WTP LIN tted to AFMSS for processing b	/IITED PTNRSHIP, sent to	the Carlsbad	NMOCD ARTESIA		
Name(Printed/Typed) JENNIFEF	A DUARTE	Title REGUL	ATORY SPECIALIST			
Signature (Electronic S	ubmission)	Date 10/17/2	013			
	THIS SPACE FOR F	EDERAL OR STATE		ROVED		
Approved By		Title	— //nct	205 2000		
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent would entitle the applicant to conduct	table title to those rights in the subject operations thereon.	ct lease Office	Mana	# / (ONOM)		
itle 18 U.S.C. Section 1001 and Title 43 U.States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a crime atements or representations as to any	for any person knowingly and matter within its jurisdiction.	willfully to make to any departments) နုဋ္ဌင်္ကေလ of the United		

Additional data for EC transaction #223354 that would not fit on the form

32. Additional remarks, continued

OCD records (CP1)

6- Displace 25 Bbls 10 ppg mud above the cement plug. Pull to 8200?
7- Spot 36 Sx of class ?H? cement of 15.6 ppg from 8200? to 8000?. Flush the tubing with fresh water and pull 120?

8- WOC 8 hours, then RIH and tag the cement plug that cover Strawn formation top. Note depth for OCD records (CP2)

9- Displace the well with 10 ppg mud.
10- Perform a BLM PET witnessed (charted) casing integrity test of 500 psi.

Perforating
11- RU Wireline unit with full lubricator
12- RIH CCL and gun to perforate Cisco in the interval 7430?-7850?

13- RD Wireline unit.

Acid Stimulation
14- RIH 7" RBP and 7" packer on working string
15- Acid stimulate Cisco perforations with 16,000 glns 15%HCL plus 0.2% corrosion inhibitor, 0.2% surfactant, and 0.4% iron control. Displace with fresh water. Rate 5 bpm.

16- Open tubing and flow back until dead. Unset packer, Latch and unset RBP, Reverse out until balance columns.

17- POH. LD packer and RBP.

Permanent Completion

18- MU & RIH tubing with tubing anchor
19- Land tubing hanger. ND BOP. NU Pumping Tree

20- RIH rod pump on rod string.
21- Install ROTAFLEX Unit.
22- Test pump function
23- Rig Down. Put the well on production.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Phone: (505) 476-3460 Fax: (505) 476-3462

API Number

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office


³ Pool Name


Certificate Number

WELL LOCATION AND ACREAGE DEDICATION PLAT

² Pool Code

3	30-015-28621	621 Dagger Draw; Upr. Penn, South							
4 Property	Code	⁵ Property Name					⁶ Well Number		
		North Indian Basin Unit 21							
OGRID 1					8 Operator				⁹ Elevation
16696					OXY USA				3747' GL
	γ			r	¹⁰ Surface				
UL or lot no.	Section 11	Township	Range 23E	Lot Idn	Feet from the	North/South line	Feet from the 1815'	East/West line WEST	County EDDY
F]**	215	<u> </u>				<u> </u>	WEST	EDDA
" Bottom Hole Location If Different From Surface									
UL or lot no.	Section	Township	Range	Lot Id	n Feet from the	North/South line	Feet from the	East/West	t line County
12 Dedicated Acre	s ^{[13} Joint o	r Infill	onsolidation	Code 15	Order No.	1	L		
320									
No allowable division.	will be ass	signed to th	is comple	tion until	all interests have	been consolidated	or a non-standa	rd unit has bee	en approved by the
16							17 O	PERATOR C	ERTIFICATION
							II	•	contained herein is true and complete
							- 1	-	ef, and that this organization either
							II.	-	nineral interest in the land including has a right to drill this well at this
							11		an owner of such a mineral or working
 		2245					_		reement or a compulsory pooling
		1 2				-	<i>2</i> 11 (ore entered by the divisio	
							THE AY	n m V da	06/10/2013
7							Signature	VIYY	Date
				1			Printed Nam		
1815	•	\							
1013		>0					Jennifer dua E-mail Addr	une@oxy.com ess	
				n	9	1			
				7			"SUR	VEYOR CE	RTIFICATION
							I hereby c	ertify that the wel	ll location shown on this
] .			plat was p	olotted from field i	notes of actual surveys
I							made by n	ne or under my su	ipervision, and that the
							ll -	•	the best of my belief.
									marata y my army.
							Date of Sur	vev	
							H	nd Seal of Profession	nal Surveyor
							3181ធារិយិត ព	" oral of Linessing	mi om rejoi.
						1			
		1							
1		1					l		





North Indian Basin Unit 21 30-015-28621 OXY USA Inc. October 25, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by January 1, 2014.

- 1. Operator shall Tag cement plug at 8,846'.
- 2. Cement procedure is approved as written.
- 3. Must conduct a casing integrity test to maximum treating pressure before any perforating or fracturing is done. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 4. If CIT passes operator can recomplete as proposed.
- **5.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Surface disturbance beyond the originally approved pad must have prior approval.
- 7. Closed loop system required.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Operator to have H2S monitoring equipment on location.
- 10. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 11. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 12. See attached for general requirements.

JAM 102513

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement.

Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.