Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM89819

SUNDRY NOTICES AND REPORTS OF	WELLS 2013
Do not use this form for proposals to drill or abandoned well. Use form 3160-3 (APD) for s	ove-enter an
abandoned well. Use form 3160-3 (APD) for si	ieh proposals AHTES A

Do not use this form for proposals to drill or toyle, enter an abandoned well. Use form 3160-3 (APD) for such proposals ARTESIA			ESA 6. If Indian, Allot	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRII	PLICATE - Other instructions o	on reverse side.	7. If Unit or CA/A	Agreement, Name and/or No.	
1. Type of Well			8. Well Name and		
☑ Oil Well ☐ Gas Well ☐ Other			PATTON 18 F	-EDERAL 8H	
Name of Operator OXY USA INCORPORATED	STEWART		9. API Well No. 30-015-41343-00-X1		
3a. Address 5 GREENWAY PLAZA STE 1 HOUSTON, TX 77046-0521	one No. (include area code 32.685.5717) 10. Field and Poo. COTTON DR	10. Field and Pool, or Exploratory COTTON DRAW		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Par	11. County or Parish, and State	
Sec 18 T24S R31E SWSE 150FSL 1700FEL			EDDY COUI	EDDY COUNTY, NM	
12. CHECK APPR	ROPRIATE BOX(ES) TO INDI	CATE NATURE OF	NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	□ Deepen	☐ Production (Start/Resume) Water Shut-Off	
_	☐ Alter Casing [☐ Fracture Treat	□ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	□ Temporarily Abandon		
	☐ Convert to Injection	□ Plug Back	■ Water Disposal		
Halliburton which we are confi any particulates will seal the le and ductile qualities which will treatment and production of hy request to complete this well a submitted electronically for rev be submitted with completions plan forward for this well?s rer considered and included in thi activities are conducted as de they were intended.	quests to repair the leak on the D dent due to the nature of the liqueak and develop into a cement we enable the cement seal to withs ydrocarbons. Pending the remed as outlined below. Documentation view on 9/16 and 9/5 respectively a reports. This notice of intent hamediation and completion. Additionally sproposed plan to provide reason signed, and stimulation fluids are	uid resin polymer netwith adequate compresistand the pressure of a liation and positive prended the hard copies of the salso been requested onal safety factors hard conable assurance that	ork without sive strength fracture ssure test, we CBL-VDL was ne CBL will I to review the ve been well stimulation n for which	NOV 6 2013 NOV 6 2013 EAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE CARLSBAD FIELD OFFICE	
14. I hereby certify that the foregoing	INDIONIC OF LEGIS	7 A T			
	Electronic Submission #221149	VAT verified by the BLM We RPORATED, sent to the	e Carlsbad	Accepted for re	
	E SPEARS		LETIONS ENGINEER	(b) NMOCD	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	2 0, 2, 1, 10	3333	EETTOTO ETTOTICETT	11/13/13	
Signature (Electronic S	Submission)	Date 09/25/2	2013		
	THIS SPACE FOR FEI	DERAL OR STATE	OFFICE USE		
Approved By EDWARD FERNAN	DE7	TitleDETDOL	EUM ENGINEER	Date 11/06/2013	
Conditions of approval, if any, are attache terrify that the applicant holds legal or equivalent would entitle the applicant to conductive the	d. Approval of this notice does not warn	rant or		11100/2010	
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime fo	r any person knowingly and	d willfully to make to any departmen	nt or agency of the United	

Additional data for EC transaction #221149 that would not fit on the form

32. Additional remarks, continued

OBJECTIVE: Repair the leaking DV-Tool and pressure test casing as per BLM requirements, Following successful pressure test which can be witnessed by BLM representatives, proceed to stimulate and complete horizontal 2nd Bone Springs well in 6 stages w/ 4 entry points per stage. Frac method will be Plua & Perf.

JOB NOTES ON EXECUTION:

Operator will continuously monitor and record the pressure(s) during the well stimulation operations.

Pressure will be contained in the string through which the stimulation is being pumped (5-1/2", 20#, L-80 casing)

Annulus pressure will be monitored throughout job -5%

If during the stimulation operation the annulus pressure increases by more than 500# over the annulus pressure immediately preceding the stimulation, the job will be shut-down and the BLM notified as soon as possible. Anticipated Treating Rate:50-60 BPM - Anticipated WHTP:5650# -Anticipated Maximum Pressure:6200#

If during the stimulation operation, the WHTP should exceed 6690#, all pumps will be shut-down so as not to apply greater than 7192# on the casing (or no greater than 80% of burst at ANY TIME) and will move on to the next stage.

Treat via: 5-1/2", 20#, L-80 casing (8990# Internal Yield Pressure)

PROPOSED OPERATIONS:

1. MIRU Wireline

* SeenA Set 4.4"OD Peak EZ-Drill Composite Bridge Plug @ 4295' and dump 2sx cement

3. RDMO

MIRU Pulling Unit

Mix 10 bbls of Well-Lock in batch mixer on location

6. PU 2?7/8" 6.5# Tubing

Balance Spot Well-Lock across 4268?4488' through tubing

Pull up 1000' above plug and pressure up to required pressure(based on lab testing)

9. Bleed down pressure to 500# and shut-in well for time required to establish compressive strength development

10. Drill-out cement and composite bridge plug and clean-out to PBTD.

11. Pressure test casing to 6293# for 30 min. (BLM representative to witness pressure test, if

12. Increase pressure to 7192# and hold for 10 min. (BLM representative to witness pressure test, if required)

13. Make a run with Watermelon Mill.

13. Make a run with watermeiori will.

14. RDMO Pulling Unit

15. MIRU 2" Coiled Tubing Unit

16. PU TCP guns on 2" CT & TIH to perforate the toe ? fire guns hydraulically. Guns are 3.125" SDP-3375-311NT, 21.5gm chg, 0.39" EHD, 35.6" penetration w/ 6 JSPF on 60 degree phasing. Perforate first stage as per design w/ 39 holes. POOH w/ CT. RDMO CT Unit. 17. Set and load frac tanks.

17. Set and load frac tanks.

18. RU Frac Unit & WL. Frac stage 1 down casing as per service company frac procedure: Proposed Stage Volumes - 5000gals 15% HCl Acid, 173,700gals gel, 239,000# 20/40 proppant - Proposed Total Job Volumes (6 stages) - 20,000gals 15% HCl Acid, 1,042,200gals gel, 1,434,000# 20/40 proppant.

19. RU WLU and set CBP between stages. Perf the next stage as per design w/ 3.125" Titan EXP-3319-322T charge. 0.39" EHD, 40.56" penetration w/ 6 JSPF on 60 degree phasing, 35 total holes.

20. Repeat steps for stages 2-6

CONDITIONS OF APPROVAL

Sundry dated 09/25/2013 Repair leak at DV tool and completion

OPERATOR'S NAME:

OXY USA INC

LEASE NO.: | NM89819

WELL NAME & NO.:

8H Patton 18 Federal 150' FSL & 1700' FEL

SURFACE HOLE FOOTAGE:

330' FNL & 1700' FEL

BOTTOM HOLE FOOTAGE LOCATION:

Section 18, T.24 S., R.31 E., NMPM

COUNTY: |

Eddy County, New Mexico

- 1. Surface disturbance beyond the existing pad shall have prior approval.
- 2. Functional H₂S monitoring equipment shall be on location.
- 3. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 4. Notify BLM 575-200-7902, if there is no response, 575-361-2822 as work begins and provide sufficient time to allow BLM to witness casing integrity test after repairing leak at DV tool. If no answers leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5. Operator's procedure Step 11: perform a BLM PET witnessed (charted) casing integrity test. Pressure leakoff may require remediation prior to continuing the frac. Include a copy of the chart in the subsequent sundry for this work.
- 6. Operator shall be required to run CBL/VDL/Ultrasonic Bond Log from lowest attainable depth to surface (this CBL shall be ran after the casing repair). Provide BLM with an electronic copy (Adobe Acrobat Document) of CBL.
- 7. All other types of pressure testing of casing shall be chart recorded for 30 minutes and submit a copy of the chart in the subsequent sundry for this work.

Reminder

8. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp <jchopp@blm.gov> 575.234.2227 or Bob Ballard <bballard@blm.gov> 575.234.5973.

Work to be completed within 90 days EGF 110613