			•	
Submit 1 Copy To Appropriate District Office	State of New Me	xico		Form C-103
<u>District I</u> – (575) 393-6161	rict 1 – (575) 393-6161 Energy, Minerals and Natural Resources		VELL API NO.	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-015-10414	
811 S. First St., Ártesia, NM 88210 District III – (505) 334-6178	First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		. Indicate Type of Lea	ase
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE S FEE	
District IV – (505) 476-3460 Salita Fe, INIVI 87303 1220 S. St. Francis Dr., Santa Fe, NM		505	6. State Oil & Gas Lease No. VA-636	
87505	EC AND DEPORTS ON WELLS	7		A Nome
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			<ul> <li>Lease Name or Unit Archimedes SWD</li> </ul>	Agreement Name
DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)		D CHCH	. Well Number	
· _	Gas Well  Other SWD		1	
2. Name of Operator		9	. OGRID Number	
Yates Petroleum Corporation  3. Address of Operator		1	025575 10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210		1	SWD; Devonian	
4. Well Location			·	
Unit Letter J : 16	feet from the South	line and198	feet from the	<u>East</u> line
Section 18	Township 21S Rar	<u> </u>	IMPM Eddy	County
	11. Elevation (Show whether DR,			
以及其實際的發展。其後發展者的的學術質量	3,838'	KB		
12 Charle Ar	annonviata Day ta Indianta N	otura of Notica Do	mort or Other Date	
12. Check Ap	opropriate Box to Indicate Na	ature of Notice, Re	eport of Other Data	l
NOTICE OF INT			EQUENT REPOR	
<del></del>	PLUG AND ABANDON	REMEDIAL WORK		ERING CASING
<del></del>	CHANGE PLANS  MULTIPLE COMPL	COMMENCE DRILLI CASING/CEMENT J		ND A
DOWNHOLE COMMINGLE	MOLTII EE COMI E	CASH CASH ST		
CLOSED-LOOP SYSTEM	· _			
OTHER:	ted operations. (Clearly state all p	OTHER: Repaired of		Juding estimated data
	k). SEE RULE 19.15.7.14 NMAC			
proposed completion or recor		1		5
12/3/13 – NU BOP				
	aper and TIH. Picked up tubing to	o 200'. POH. Picked	up 7" packer and RBF	to 650'. Set plug to
test casing. Circulated out 7"	x 9-5/8". Released RBP. TIH to			
dropped to 400 psi quickly w			. 1000 - 1 11 - 1	C 10 '
	I and set packer RT on top of RBF p to 5,243'. Tested across casing			
	good to 500 psi. TIH and perf'd 4			
	ng up 7" x 9-5/8". POOH with AI	D-1 packer. Released	and pulled RBP up to	2,241'. Tested to
1000 psi, good. POOH with	packer. Dump sand on RBP.			
		CONTINUED ON N	NEXT PAGE:	RECEIVE
			j	POLIVE
				JAN 03 2014
Spud Date:	Rig Release Da	te:	-	N'MOCD ARTES
			,328	TOO ARTES
I hereby certify that the information ab	ove is true and complete to the be	est of my knowledge a	nd belief.	
1- 1				
SIGNATURE SUMC	TITLE Regu	latory Reporting Tech	nnician DATE <u>De</u>	cember 31, 2013
Type or print name Laura Watt	ts E-mail address: la	ura@yatespetroleum.c	om PHONE: _	_575-748-4272
		4		11. 9
APPROVED BY: A CHARO	THE COMP	UNNUE OFFICET	DATE_	1/3/14
Conditions of Approval (if any):				I. /

Archimedes SWD #1 Section 18-T21S-R24E Eddy County, New Mexico Page 2

## Form C-103 continued:

12/8-9/13 – Set 7" cement retainer at 1,910'. Pumped down tubing and broke up 7" x 9-5/8". Batched up "C" cement, 1.32 yld, 14.8#. Circulated 300 sacks of cement to surface. Stung out retainer. POOH with tubing. Loaded hole with fresh water. Pumped surface plug to cover hole at surface. Wait on cement to cure.

12/10/13 – Did not tag surface plug. Well began circulating out 7" x 9-5/8". POOH with collars. Could see 2 holes in 7" casing 1' from surface. Batched up "C" cement with calcium. Poured down 7" x 9-5/8" until cement was coming out of holes in 7". Topped off 7" with cement at that time with 2' cement plug.

12/11/13 – Did not tag surface plug, was standing full of fluid. Had good cement on 7" x9-5/8" coming off side where 2" nipple was. Began pumping with 1" valve on other side of wellhead off 7" x 9-5/8". Filled 1" with cement and shut valve. Pressure tested to 500 psi and lost 60 psi down to 440 psi in 10 mins. Got 1 hole sealed off. Hand mixed cement and poured down 2" nipple down 7" x 9-5/8". Could not get cement to run into casing. Hooked up reverse unit kicking pump in and out to push cement into casing. Filled inside of 7" with cement.

12/12/13 - Drilled out surface plug. Tested casing with all surface valves open to 500 psi. Lost 60 psi in 10 mins and 130 psi in 30 mins. Set packer. Tested casing down tubing to 500 psi, held good. ND BOP.

12/15/13 – Dug out cellar. Install new 7" casing and 9-5/8" casing stubs.

12/16/13 – NU BOP. Loaded hole and test casing to 560 psi, held good for 10 minutes.

12/17/13 - Tagged cement at 1,875'. Tagged retainer at 1,903'. Circulated clean.

12/18/13 - Drilled out cement and fell out at 1,992'. TIH with RBP. Circulated sand off RBP. POOH with tubing. TIH with ret tool. Tagged RBP. Circulated off top of RBP. Latched up to RBP and had gas bubble come to surface. Blow down well for 30 mins. Released RBP.

12/19-24/13 – Moved out 2-7/8" workstring. Moved in 4-1/2" PC buttress tubing. Circulated hole with packer fluid. Stung seal assembly in liner hanger and flanged well up. Was told to call Richard with NMOCD and he said he would be out of town – go ahead and test the well and send in the chart. Did not have to witness. Pressured casing to 485 psi and dropped down to 460 psi in 30 mins. Should be good with allowed 10% loss.

12/25/13 – 4-1/2" 11.6# N-80 tubing at 5,995'. Turned well over to production.

Original MIT chart attached

Regulatory Reporting Technician

Décember 31, 2013

