

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. **NM 030752**
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well
Oil Well Gas Well Other **SWD**

2. Name of Operator **Ray Westall Operating Inc.**

3a. Address **P.O. Box 4 Loco Hills, NM 88255** 3b. Phone No. (include area code) **(575) 677-2370**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1650' ENL & 660' FEL, S 27, T 18S, R 29E, U1C-H

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No. **Empire A Federal # 2 SWD**

9. API Well No. **30-015-29618**

10. Field and Pool or Exploratory Area

11. County or Parish, State **Eddy County, NM**

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
<input type="checkbox"/> Subsequent Report	Casing Repair	New Construction	Recomplete	<input checked="" type="checkbox"/> Other Apply tank coating not of BLM color
	Change Plans	Plug and Abandon	Temporarily Abandon	
<input type="checkbox"/> Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Ray Westall Operating, Inc. intends to apply protective graphite coating to the fiberglass tank(s). This coating is gray in color, but will reduce static electricity. This, in turn, will reduce the chance of the tank(s) being struck by lightning and prevent loss of fluids.

Accepted for record
NMOCD *TES*
5/14/14

RECEIVED
MAY 12 2014
NMOCD ARTESIA

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Rene Hope** Title **Bookkeeper**

Signature *Rene Hope* Date **3/28/14**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *[Signature]* Title **PET** Date **05/06/2014**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office **CFO**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)