

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
100 Rio Brazos Road, Aztec, NM 87410  
District IV  
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

APR 22 2014

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

nHMP1412224328

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 224137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Way South State Com #001H	Facility Type	Tank Battery

Surface Owner State	Mineral Owner	Lease No. (API#) 30-015-37234
---------------------	---------------	-------------------------------

#### LOCATION OF RELEASE

Unit Letter A	Section 30	Township 26S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.01862

Longitude 104.13426

#### NATURE OF RELEASE

Type of Release Oil	Volume of Release 50bbbls	Volume Recovered 50bbbls
Source of Release Oil Tank	Date and Hour of Occurrence 04-06-2014	Date and Hour of Discovery 04-06-2014 07:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 04-07-2014 10:20am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A plug formed in the water leg on the heater treater causing the water to go in the inner oil tank. Remove plug from the water leg on the heater treater.

Describe Area Affected and Cleanup Action Taken.\*

Initially 50bbbls of oil were released. We were able to recover 50bbbls of oil with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: *Robert Grubbs Jr.*

Printed Name: Robert Grubbs Jr.

Title: Senior Environmental Coordinator

E-mail Address: rgrubbs@concho.com

Date: 04-21-2014 Phone: 432-661-6601

Approved by District Supervisor: *[Signature]*

Approval Date: 5/2/14

Expiration Date: NA

Conditions of Approval:

*Final*

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-2279