

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUL 16 2014

Form C-141  
Revised August 8, 2011

NMOC D ARTESIA  
Submit Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n HMP1420220008

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16699	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Amax 24 Federal #9	Facility Type	Well

Surface Owner	BLM	Mineral Owner		API No.	30-015-27411
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	24	23S	31E	1650	South	1650	West	Eddy County, NM

Latitude N 32.28728° Longitude W 103.73475°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	4 bbls oil, 6 bbls produced water	Volume Recovered	0 bbls
Source of Release	External corrosion on piping coming off stuffing box on the well head	Date and Hour of Occurrence	07/10/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOC D; Sol Hughes- BLM		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	07/11/2014 @ 3:40 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

External corrosion on piping coming off the stuffing box on the well head caused 4 bbls of oil and 6 bbls of produced water to leak onto the ground. No fluids were recovered and the piping was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 60' x 90' on the north side of the location running off location into the pasture. Remediation will be completed in accordance with a remediation plan approved by NMOC D and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by Environmental Specialist: 		
Title: HES Advisor	Approval Date: 7/21/14	Expiration Date: NA	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION		Attached <input type="checkbox"/>
Date: 7-16-14 Phone: (575) 397-8216			

\* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

8/21/14

2RP-2379